

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2026

Submitted Date:

05/05/2026

Document Number:

719700675

FIELD INSPECTION FORM

Loc ID: 420598 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
 Name of Operator: NOBLE ENERGY INC
 Address: 1099 18TH STREET SUITE 1500
 City: DENVER State: CO Zip: 80202

Findings:

11 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420601	WELL	TA	02/01/2022	OW	123-32644	BASHOR PC AA 09-23	TA

General Comment:

This is a WELL audit. (AMA: Alternate Method Audit).
 Well(s): 1: Temporarily Abandoned | TA.
 Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (420596, 420598).
 (Well(s): 2: Temporarily Abandoned | TA).

Centralized Battery formerly served 1 Location ID (420599).
 (Well(s): 1: Plugged & Abandoned | PA).

Centralized Battery serves 1 Tank Battery Facility ID (481647).

- *Follow-up to Field Audit Report doc. #719700549 dated 03/26/2026.
- *Follow-up to FIR Resolution Form (FIRR) doc. #404604778 dated 04/01/2026.
- *Follow-up to FIR Resolution Form (FIRR) doc. #404629151 dated 04/21/2026.

*This is an audit of the scout card and related documents followed by an AMA. (Alternate Method Audit).

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	<p>*Prior audit: CORRECTIVE ACTION ITEM(s): During this audit the following possible compliance issue(s) were observed: Emergency contact number with Company & Well Name NOT posted at wellsite. Refer to Rule 605.d for guidance. *Post emergency contact number with Company & Well Name at wellsite. Comply with Rule 605.d. (30-days). CA date: 04/27/2026. *This audit: Posted. Blue TA tag posted. OOSLAT applied at well, separator(s). *Refer to Emergency Contact Number section below.</p>		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<p>Posted. **This audit: *FIR Resolution Form FIRR doc. #404629151 asserts: Wellsite signage w/ Company, well name, Emergency # has been posted as of 04/21/2026. Operator provided photo for verification. See photo(s) #1-4.</p>		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	<p>*Prior audit: CORRECTIVE ACTION ITEM(s): During this inspection the following possible compliance issue(s) were observed: 1.) Undesirable vegetation at wellsite(s). (Weeds). Refer to Rule 606.c for guidance. *Remove, manage, & control undesirable vegetation around wellsite(s). Comply with Rule 606.c. (30 days). CA date: 04/27/2026. **This audit: *FIR Resolution Form FIRR doc. #404604778 asserts: Undesirable vegetation at wellsite(s). (Weeds). Has been mitigated as of 04/01/2026. Operator provided photo for verification. See photo(s) #1-4.</p>		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead # 1			corrective date
Comment: Appears plumbed to surface.			

Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead: w/ Master, casing valves.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.504389,-104.432704
Comment:	Centralized Battery serves 2 Location IDs (420596, 420598). (Well(s): 2: Temporarily Abandoned TA). Centralized Battery serves 1 Tank Battery Facility ID (481647).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 420601 Type: WELL API Number: 123-32644 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Locked-Out, Tagged-Out | LOTO.
Blue TA tag posted.
OOSLAT applied at well, separator(s).
ECMC records last prod: 01/2015.

Form 4 on file. TA date: 11/30/2020. Approved.
DH-quartzpack plug.
Form 21 MIT on file. Date: 02/07/2020. Approved.
Form 6A on file. Out-of-Svc Designation. Approved.
Date ceased prod: 06/05/2020.

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 03/17/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments		
Comment	User	Date
<p>CECMC Audit Report Synopsis:</p> <p>On MON 05/04/2026 at approximately 15:30 hrs. I, Bret Evins, conducted an AMA: Alternate Method Audit at: Operator Name: NOBLE ENERGY INC Location Name: BASHOR PC AA/09-23 Location ID: 420598 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>Audit observations: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>* While conducting this audit, the following prior possible compliance issues appear to be addressed: *CORRECTIVE ACTION Item(s) RESOLUTION Comment: 2 1. Refer to pg 2, "Good Housekeeping" section of this report. **FIR Resolution Form FIRR doc. #404604778 asserts: Undesirable vegetation at wellsite(s). (Weeds). Has been mitigated as of 04/01/2026. Operator provided photo for verification. See photo(s) #1-4.</p> <p>2. Refer to pg 2, "Signs/Marker" section of this report. **FIR Resolution Form FIRR doc. #404629151 asserts: Well sign w/ Company, well name, & Emergency number has been posted as of 04/21/2026. Operator provided photo for verification. See photo(s) #1-4.</p> <p>Routine audit.</p> <p>*Any Corrective Actions from prior audits that have not been addressed remain applicable.</p>	evinsb	05/05/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719700676	Audit photo(s)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7538621