

Inspection Photos
Pete Montoya B Sales Line
Spill ID 493337/Remediation No 45017



**Photo 1 – Fencing down around open excavation.
Soil stockpile with no liner or stormwater BMPs.**

**Photo 2 – Fencing down around open excavation.
Soil stockpile with no liner or stormwater BMPs.**

Inspection Photos
Pete Montoya B Sales Line
Spill ID 493337/Remediation No 45017



Photo 3 – Open excavation. Flowlines running through open excavation. Uncapped flowlines sticking out of excavation sidewall.

Photo 4 – Open excavation. Flowlines running through open excavation. Uncapped flowlines sticking out of excavation sidewall.

Inspection Photos
Pete Montoya B Sales Line
Spill ID 493337/Remediation No 45017



Photo 5 –Flowlines running through open excavation. Uncapped flowlines sticking out of excavation sidewall.

Photo 6 – Soil stockpile with no liner or stormwater BMPs.

Inspection Photos
Pete Montoya B Sales Line
Spill ID 493337/Remediation No 45017



Photo 7 – Shallow excavation area with no fencing.



Photo 8 – Soil stockpile with no liner or stormwater BMPs.

Inspection Photos
Pete Montoya B Sales Line
Spill ID 493337/Remediation No 45017



Photo 9 – Produced water tank is cracked. Stained soil next to tank.



Photo 10 – Produced water tank is cracked. Stained soil next to tank. Weeds growing next to produced water tank.

Inspection Photos
Pete Montoya B Sales Line
Spill ID 493337/Remediation No 45017



Photo 11 – Dirt being tracked off location