

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2026

Submitted Date:

05/06/2026

Document Number:

701104750

**FIELD INSPECTION FORM**

Loc ID 334955 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261850	WELL	PR	04/16/2002	GW	045-07987	PA 333-33	EG
262387	WELL	PR	04/06/2002	GW	045-08021	PA 34-33	EG
270458	WELL	PR	06/21/2004	GW	045-09561	PA 533-33	EG
270460	WELL	PR	06/10/2004	GW	045-09560	PA 433-33	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
Weathered Danger Sign on fence at separators. Faded Danger sign on Produced water tank. Tank label is torn.  
Install sign to comply with Rule 605.g.  
Install sign to comply with Rule 605.h.  
CA Date 7/8/2026

**Location**

Overall Good:

**Signs/Marker:**

	Type TANK LABELS/PLACARDS		
Comment:	Weathered Danger Sign on fence at separators. Faded Danger sign on Produced water tank. Tank label is torn.		
Corrective Action:	Install sign to comply with Rule 605.g. Install sign to comply with Rule 605.h.	Date:	07/08/2026

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No \_\_\_\_\_

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 261850 Type: WELL API Number: 045-07987 Status: PR Insp. Status: EG

Facility ID: 262387 Type: WELL API Number: 045-08021 Status: PR Insp. Status: EG

Facility ID: 270458 Type: WELL API Number: 045-09561 Status: PR Insp. Status: EG

Facility ID: 270460 Type: WELL API Number: 045-09560 Status: PR Insp. Status: EG

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104751	Flowline integrity inspection 701104750 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7540034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7540034</a>