

RESOLVED PHOTOS – HUBER LOBATO 1-26



<b>Today's Date:</b>	4/29/2026					
<b>Well Name:</b>	HUBER-LOBATO 1-26	<b>Location:</b>	Sec: 26	Twn: 035N	Rng: 008W	UL: F
<b>API Number:</b>	05.067.07551	<b>Footage:</b>	2290' FNL & 2005' FWL			
<b>Operator:</b>	Hilcorp Energy Company	<b>Area/Run/MSO:</b>	01	0100	Bob Percell	
<b>Meter #:</b>	DR0507RF		<b>Pipeline:</b>	HEC		
<b>INC Number:</b>	719001840	<b>Agency:</b>	ECMC	<b>Inspector:</b>	CHARLES GARCIA	
<b>Type of INC:</b>	Written	<b>Photos Required:</b>	<b>Yes</b>	<b>Due Date:</b>	<b>5/5/2026</b>	
<b>Issue of Concern:</b>	<p><b>Comment:</b> EAST SIDE OF LOCATION UNUSED EQUIPMENT AND 5 GAL LEAKING BUCKET SEE LOCATION PICTURES  <b>Corrective Action:</b> Unnecessary equipment COMPLY WITH RULE 606</p> <p><b>Comment:</b> LEAK ON ENGINE FOR PRIME MOVER HAS CAUSED OIL TO LEAK ON BOTH SIDES OF ENGINE SKID  <b>Corrective Action:</b> MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND PRIME MOVER SKID rule 1002.f</p>					

