

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2026

Submitted Date:

05/06/2026

Document Number:

719001951

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325560 \_\_\_\_\_ GARCIA, CHARLES \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

**Findings:**

- 8 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		mollieo@maralexinc.com	<a href="#">All Inspections</a>
Kosola, Jason		jason.kosola@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
,		pbechtolt@maralexinc.com	
Longworth, Mike		mike.longworth@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443485	TANK BATTERY	AC	10/02/2015		-	Campbell Tank Battery	AC

**General Comment:**

[Inspection Report Summary](#)  
On 5/5/26 I Inspector Charles Garcia conducted an on-site inspection.  
Location: CAMPBELL TANK BATTERY  
OPERATOR: MARALEX RESOURCES INC  
FACILITY ID:#215004  
County: LaPlata  
All prior CA's still stand

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANKS		
Corrective Action:		Date:	
Type	OTHER		
Comment:	The tank battery is signed as "Katie-Eileen Tank Battery" see location pictures but there is no facility in COGIS with this name. Campbell Tank Battery is in COGIS with coordinates in the same area and it is unclear if the facility has changed ownership". SEE LOCATION PICTURES		
Corrective Action:	Install sign or correct sign per rule 605	Date:	05/08/2026

**Emergency Contact Number:**

Comment:	970-563-4000 911 EMERGENCY	Date:	
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			
Produced Water	Flow Line	<= 1 bbl			
Comment:	Large wash out filled with water approximately 2.5 ft deep inside of berm. The source of the discolored free fluid is unclear and may be coming from a flowline leak. Due to the base of secondary containment being excavated/washed out. I also found deer tracks leading up to the spill and a dead deer on the side of tank battery. SEE LOCATION PICTURES.				
Corrective Action:	"Remove free fluids "because fluid is discolored it must be handled and disposed of as waste". Also determine source of fluids release, a flowline pressure test may be required, stop/prevent further fluids releases. Fluids released and absorbed greater than 1 bbl require Form 19 spill report and follow up with SW EPS Jason Kosola per Rule 906"			Date:	05/08/2026

In Containment: Yes

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLS	PBV STEEL		37.122835,-107.592306
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate	
Comment:	Large wash out filled with water approximately 2.5 ft deep inside of berm in north east corner possible flow line leak. SEE LOCATION PICTURES				
Corrective Action:	Repair secondary containment where excavated/washed out to ensure structure is significantly impermeable per Rule 603.0". There is light colored mineral rind indicative of past produced water releases".			Date:	05/08/2026

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 443485 Type: TANK API Number: - Status: AC Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

UIC Routine

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: \_\_\_\_\_  
 TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: \_\_\_\_\_  
 Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
2 corrective actions related to possible flow line leak 1 corrective action for signage of tank battery. REFER TO COMMENTS AND LOCATION PICTURES	garciacr1	05/06/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001958	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7540242">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7540242</a>