

Inspection Photos

Operator: **GUNNISON ENERGY LLC – 10515**

Location Name: **ALLEN 1291 12-24**

Location ID: **322002** API #: **05-029-06091**

Inspection Date: **5/4/2026** Inspection Doc#: **693809266**



Location overview looking SW



Tank Battery

Inspection Photos

Operator: **GUNNISON ENERGY LLC – 10515**

Location Name: **ALLEN 1291 12-24**

Location ID: **322002** API #: **05-029-06091**

Inspection Date: **5/4/2026** Inspection Doc#: **693809266**



Off location flowline risers



Separator and Generator

Inspection Photos

Operator: **GUNNISON ENERGY LLC – 10515**

Location Name: **ALLEN 1291 12-24**

Location ID: **322002** API #: **05-029-06091**

Inspection Date: **5/4/2026** Inspection Doc#: **693809266**



Electrical Control panel



Excavations for Plugged and Abandoned well.

Inspection Photos

Operator: **GUNNISON ENERGY LLC – 10515**

Location Name: **ALLEN 1291 12-24**

Location ID: **322002** API #: **05-029-06091**

Inspection Date: **5/4/2026** Inspection Doc#: **693809266**



Cut off wellhead and valves



Tubing and Sucker rods from Plugged and Abandoned well