

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

04/30/2026

Document Number:

709100652

FIELD INSPECTION FORM

Loc ID: 317307 Inspector Name: Heibel, Krystal On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 20275
Name of Operator: CORAL PRODUCTION CORP
Address: 1600 STOUT ST STE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Steve Chonka		schonka08@gmail.com	
Anthony Dunnam		anthony.dunnam@state.co.us	
James Chonka		jpchonka@netscape.net	
Krystal Heibel		krystal.heibel@state.co.us	
Marjorie Wallace		marjoriwallace@comcast.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270974	PIT	AC			-	LINDA #1 PIT #1	EI
270975	PIT	AC			-	LINDA #1 PIT #2	EI
271944	PIT	AC			-	LINDA 1 PIT 3	EI
317307	LOCATION	AC			-	LINDA-62S52W 19SESE	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. On April 9, 2026, ECMC Staff Krystal Heibel and Alex Ahmadian conducted an environmental remediation inspection at this location. To refer to the previous reclamation inspection, conducted on Feb 25, 2026, refer to Doc# 718601412.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: T-posts and metal pipe remain in the pits. Electrical equipment, pipe, posts and wood debris remain on the wellbore location. See attached photos.

Corrective Action:

Date:

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 270974 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 270975 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 271944 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 317307 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: For Remediation Project #22462, ECMC has not received Form 27 Supplemental reports in greater than 90 days. The most recent Form 27S received for REM 22462 was 12/14/2023. Operator shall submit a Form 27 Supplemental for the Remediation Projects as soon as possible, in order to regain compliance with Rule 913.e.(3). CORAL PRODUCTION CORP will remain in violation of Rule 913.e.(3) until these Form 27S are approved by the Director. Reach out to NE Area EPS Krystal Heibel(krystal.heibel@state.co.us) if you have any questions.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: 03/13/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404642381	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533877
709100653	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533876