

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2026

Submitted Date:

04/30/2026

Document Number:

710500775

FIELD INSPECTION FORM

Loc ID: 443255 Inspector Name: Sanchez, Chris On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
7 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10412
 Name of Operator: AUSCO PETROLEUM INC
 Address: 113 N SANTA FE AVENUE
 City: FLORENCE State: CO Zip: 81226

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beardslee, Tom		tom.beardslee@state.co.us	
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	All Inspections
Harkins, Liz	719-429-4513	Lharkins@austinexploration.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
443256	WELL	PR	08/01/2020	OW	043-06229	Magellan 1	EI

General Comment:
 This is a follow up Environmental Inspection for the Magellan # 1 well location in Florence County, Colorado.
 API # 05-043-06229
 Location ID: 443255
 Inspection # 710500681
 Inspection # 710500731

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well Placard located at the wellhead, well name is not legible		
Corrective Action:	Install sign to comply with Rule 605.g. Original correctibe action date shall apply	Date:	03/16/2026
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
Good Housekeeping:			
Type	OTHER		
Comment:	At the time of inspection, impacts to soils were observed within the tank battery containment. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Other	WELLHEAD		
Comment:	At the time of inspection, an audible gas leak was noted at the wellhead. ECMC staff messaged Ausco Petroleum Emergency Contact, (Liz Harkins), regarding the suspected gas leak.		
Corrective Action:	Operator shall provide documentation showing the leaking wellhead was repaired. Original Corrective Action Date shall apply	Date:	02/02/2026
Lube Oil	Pump Jack		
Comment:	At the time of inspection, oily liquids were observed on the base of the pumping unit adjacent to the engine skid.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. Original Corrective Action Date shall apply	Date:	01/16/2026
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Venting:			
Yes/No	<input style="width: 100%;" type="text"/>		
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		
Date: _____			
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 443256 Type: WELL API Number: 043-06229 Status: PR Insp. Status: EI**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404642309	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533799
710500776	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533796