

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2026

Submitted Date:

04/30/2026

Document Number:

710500777

FIELD INSPECTION FORM

Loc ID: 439554
Inspector Name: Sanchez, Chris
On-Site Inspection:
2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 4 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 10412
 Name of Operator: AUSCO PETROLEUM INC
 Address: 113 N SANTA FE AVENUE
 City: FLORENCE State: CO Zip: 81226

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Harkins, Liz	719-429-4513	Lharkins@austinexploration.com	All Inspections
Waggoner, Kyle		kyle.waggoner@state.co.us	
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439553	WELL	PA	08/04/2025	OW	043-06228	Marco Polo 1	EI

General Comment:
 This is a follow up environmental inspection for Marco Polo 1, well location located in Fremont County, Colorado.
 API # 05-043-06228
 Location ID 439554, Pathfinder C-18 4
 Remediation Project # 41047
 Inspection # 710500679
 Inspection # 710500729

Inspected Facilities

Facility ID: 439553 Type: WELL API Number: 043-06228 Status: PA Insp. Status: EI

Environmental

Spill/Remediation:

Comment: This is an Environmental Inspection for Remediation Project # 41047. At the time of inspection, the remediation excavation was backfilled.

Initial Form 27-I was submitted on 06/18/2025 and approved on 06/30/2025.

Operator has not provided analytical data for Remediation Project # 41047 to confirm the presence or absence of impact to soils within the wellhead excavation.

The approved reporting schedule was identified as 90 days after receipt of analysis. Form 6-S document no. 404300609 indicates the well was cut and capped on 8/04/2025. Operator shall submit Supplemental Form 27-S in accordance with the reporting schedule approved in Form 27-I document no. 404245195.

Corrective Action: In accordance with Rule 913.e., Operator will adopt a quarterly reporting schedule (every 90 days) Previously assigned corrective action date shall apply 01/30/2026 Date: 01/30/2026

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404642310	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533800
710500778	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533797