

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

04/21/2026

Document Number:

712300283

FIELD INSPECTION FORM

Loc ID 436485 Inspector Name: Maxwell, Logan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10421
Name of Operator: PETROLEUM RESOURCE MANAGEMENT CORP
Address: 1110 SOUTH VINE STREET
City: DENVER State: CO Zip: 80210

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		hhill@fieldinghillllc.com	
		jmckinley@fieldinghillllc.com	
		chris@fieldinghillllc.com	
		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436485	LOCATION	AC			-	WPU-36 1	RI

General Comment:

On 4/09/2026, Acting Reclamation Supervisor Trujillo and NW Reclamation Specialist Maxwell conducted a reclamation and sormwater inspection at PRM's WPU 36-1 Oil and Gas Location, ID: 436485, in Moffat County, Colorado. Staff met with Operator representatives on-site to discuss any outstanding compliance issues.

This inspection is a follow-up to #718600966 to document compliance with the following corrective actions:

- Weed Management
- Stormwater Management

The following compliance issues were observed during this inspection:

- Weed Management
- Stormwater management

Refer to the "Location" and "Reclamation," sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report. Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	<p>Previous inspections observed that Noxious Weeds have persisted on the Location. FIRR #404445516 stated that weed treatment was conducted in September and will be conducted during Spring 2026.</p> <p>At the time of the inspection, Staff was not able to determine the status of noxious weeds and will have to be determined as soon as environmental conditions allow. This CA remains open.</p>		
Corrective Action:	<p>Comply with Rules 606.c and 1003.f. Keep Location free of all Undesirable Plant Species. Ongoing weed monitoring/management required until Location receives a passing Final Reclamation Inspection.</p>		Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 436485 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: At the time of the last inspection, PRM was required to submit a sampling report pursuant to Rule 913.e. for Remediation Project #36128. It appears that PRM has submitted the sampling report on 3/13/2026 and remains in process. The CA to submit sampling results has been resolved.

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment During the original construction, the removal and segregation of topsoil did not meet compliance with Rule 1002.b. It was required that PRM import an approved topsoil source and place it on Location prior to interim reclamation. At the time of this inspection, it was observed that topsoil was imported. Based on drone imagery, it is estimated that approximately 13,707 CY of topsoil was imported, with a total of 15,716 CY of topsoil in the current topsoil stockpile. Staff required approximately 4,986 CY of topsoil to be imported.

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Remediation Project #36128 remains active at the time of the inspection, associated with facility closure of the tank battery.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: It was observed in Inspection #718600966, on the southeastern portion of the Location where the cuttings were originally stored and associated with Remediation Project #9706, that stormwater has commingled with E&P cuttings waste and moved onto the pad.</p> <p>It was observed in this inspection that the Remediation Project has been resolved and a silt fence was constructed as a BMP. See additional comments in "COMMENTS" section at the end of the report.</p>						Date: _____
<p>Corrective Action: _____</p>						
<p>Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT</p>						

ECMC Comments		
Comment	User	Date
It was also observed that stormwater has ponded on other areas on the southern portion of the pad and at the base of the cut slope, leading to increased infiltration and decreased pad stabilization. It was relayed to us that the Operator was bringing materials to portions of the pad to stabilize the area.	maxwell	04/17/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404640971	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7532675
712300297	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7532666