

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/28/2026

Submitted Date:

04/30/2026

Document Number:

721100367

FIELD INSPECTION FORM

Loc ID 326200 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Findings:

- 23 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------------|-------|-----------------------------------|--------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Walker, Kyle | | kwalter@enduringresources.com | All SW field inspections |
| Blair, Jamie | | jamie.blair@state.co.us | |
| Huntington, Heather | | hhuntington@enduringresources.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 216030 | WELL | SI | 05/01/2025 | CBM | 067-07636 | INDIAN CREEK WHEELER 12U-1 | SI |

General Comment:

At 10:45 hrs on Tuesday, April 28th, 2026, southwest compliance specialist Jamie Blair performed a compliance inspection and audit for the Enduring Resources Indian Creek Wheeler #12-U well. Corrective actions were identified. Photos of the inspection are included as a link in the attachments section of this document.

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access from gate approximately 1/2 mile long. Stormwater features on either side require maintenance. See stormwater section. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank has name of old operator. Photo 12. | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Well sign located near entrance to well pad. See photos 1, 3. Operator name illegible. | | |
| Corrective Action: | Properly display operator name on well sign to comply with 605. | Date: | 06/01/2026 |
| Emergency Contact Number: | | | |
| Comment: | 1(800) 916-7897 = 24 Hour call center. Confirmed by call. emergency = 911. | | |
| Corrective Action: | | Date: | |
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Several pipe segments on ground between separator and tank. Photo 14. Pumpjack out of service. Last produced water 06/2022. If pumpjack is no longer for ongoing oil and gas operations is required to comply with Rule 606. Photos 2, 6. | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Cattle panel fence. | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Cattle panel fence | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Flow Line | # 1 | | corrective date |
| Comment: | Underground from wellhead to separator. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |

| | | |
|--|-----|------------------|
| Comment: Inside same structure as vertical heated separator. Last date is 7/17/23. SI 5/1/25 | | Date: |
| Corrective Action: | | Date: |
| Type: Pump Jack | # 1 | |
| Comment: Horsehead is disconnected from walking beam and laying on ground. Polished rod removed. Pumpjack is labelled out of service. Photo 2, 6, 7, 10. | | Date: |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 1 | |
| Comment: Solar telemetry | | Date: |
| Corrective Action: | | Date: |
| Type: Other | # 1 | |
| Comment: Wellhead. Photo 5. | | Date: |
| Corrective Action: | | Date: |
| Type: Prime Mover | # 1 | |
| Comment: Gas power. Electrical controls and gas power supply do not appear to be connected. Is labelled out of service. Photo 8. 9. | | Date: |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 1 | |
| Comment: Heated separator stack. | | Date: |
| Corrective Action: | | Date: |
| Type: Deadman # & Marked | # 3 | |
| Comment: NE properly marked (photo 15). SE mrker down (photo 17), marked with fiberglass pipeline marker. SW down (photo 22). NW not found. | | Date: |
| Corrective Action: Install proper guy line markers per Rule 1003.a | | Date: 05/15/2026 |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--|---|----------|----------|---------|-----------------------|
| PRODUCED WATER | 1 | OTHER | Open Top | | 37.201296,-107.863501 |
| Comment: Operator label incorrect. Expanded metal grate on top. Appears to be empty. | | | | | Date: |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 95 BBL. |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: OK | | | | Date: |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------|----|
| Yes/No | NO |
|--------|----|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 216030 Type: WELL API Number: 067-07636 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Reported production was 04/01/2025. SI date 5/1/25. Horsehead disconnected from walking beam. Fuel and controls disconnected from prime mover. Photos 2, 5, 6, 7, 8, 9, 10.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/28/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| | | Check Dams | Fail | | | |
| Waddles | Fail | Waddles | Fail | | | |
| Ditches | Fail | Ditches | Fail | | | |
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment: Sediment is backed up behind straw wattles, and check dams are full, so water is going around and causing erosion on the location and along the access road. See photos 16, 19, 20.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 05/07/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

| Comment | User | Date |
|--|---------|------------|
| Corrective actions observed. Stormwater BMPs not functioning adequately. Well sign operator not legible. Rig anchor markers not in place. Photos included as link in attachment section. | blairj1 | 04/28/2026 |

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404641886 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533473 |
| 721100373 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533470 |