

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2026

Submitted Date:

04/30/2026

Document Number:

721100370

FIELD INSPECTION FORM

Loc ID 326660 Inspector Name: Blair, Jamie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Findings:

- 20 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Blair, Jamie		jamie.blair@state.co.us	
Walker, Kyle		kwalter@enduringresources.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	All SW Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261590	WELL	PR	05/01/2002	CBM	067-08647	WHEELER 13-4	PR

General Comment:

On Wednesday, April 29, 2026 at 10:15 AM, southwest compliance specialist Jamie Blair performed a compliance inspection and audit. The well was operating at the time of the inspection and produced water was observed leaking from the stuffing box. The operator was made aware of the issue and a pumper came promptly to address the leak. Corrective actions were issued for produced water affected soil and stormwater BMPs. Photos are included as an link in the attachments section.

Location

Lease Road:			
Type	Main		
comment:	~1/4 mile from locked gate at wheeler road.		
Corrective ActionL			Date:
Type	Access		
comment:	~200 ft long. Cattle guard at entrance to pad.		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	50 feet past cattle guard on south edge of pad.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	1-800-916-7897 or 911.		
Corrective Action:			Date:

Good Housekeeping:			
Type	OTHER		
Comment:	Produced water leak onto ground. Operator contacted stopped leak during inspection. Affected soil on ground apporximately 4 ft x 8 ft area. Photo 6.		
Corrective Action:	Conduct maintenance on equipment, and cleanup (not cover) affected material to comply with 1002.f.(2).D. Submit form 19 if more than 1 BBL was released.		Date: 05/07/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment:	No		
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	LOCATION		
Comment:	4 strand barbed wire.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	accessible		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Solar telemetry.		
Corrective Action:			Date:

Type: Vertical Heater Treater	# 0		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Operating at time of inspection.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Wellhead. Leak at stuffing box observed. Called operator, and pumper came to site immediately stopped leak.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter calibration card - 12/21/2025.		
Corrective Action:			Date:
Type: Flow Line	# 2		
Comment:	4" diameter to meter run. 2" diameter riser north of meter run may no longer be in use..		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 0		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 261590 Type: WELL API Number: 067-08647 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/29/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 8 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: accessible

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Rip Rap	Fail					
Compaction	Pass	Compaction	Pass			
Drains	Fail					
Sediment Traps	Pass					
Gravel	Pass	Gravel	Pass			

Comment: Rip rap lined drain berm in south end of pad is eroding into fill slope of pad. See photo 12. Note: sediment trap and rip-rap drain through berm on east edge is functional but is nearly full of sediment.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 05/07/2026

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Corrective actions for stormwater BMPs and produced water affected soil. See photos linked in attachments.	blairj1	04/29/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404641889	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533474
721100374	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533471