

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404648930

Date Received:  
05/07/2026

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 53255  
Name of Operator: MARALEX RESOURCES INC  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>MOLLIE O'HARE</u>	<u>970-563-4000</u>	<u>mollieo@maralexinc.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 719001934  
Inspection Date: 04/30/2026 FIR Submit Date: 04/30/2026 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: MARALEX RESOURCES INC Company Number: 53255  
Address: P O BOX 338  
City: IGNACIO State: CO Zip: 81137

LOCATION - Location ID: 333661

Location Name: KEEGAN PRTRICK-N33N7W Number: 11NWNW County: LA PLATA  
Qtrqtr: NWN Sec: 11 Twp: 33N Range: 7W Meridian: N  
W  
Latitude: 37.122550 Longitude: -107.582670

FACILITY - API Number: 05-067- -00 Facility ID: 271095

Facility Name: KEEGAN PATRICK Number: 33-7-11 #1  
Qtrqtr: NWN Sec: 11 Twp: 33N Range: 7W Meridian: N  
W  
Latitude: 37.122550 Longitude: -107.582670

CORRECTIVE ACTIONS:

**1** CA# 212602

Corrective Action: 608.e MAINTAIN LUBRICATION SYSTEM CLEAN UP IMPACTED SOIL AROUND WELLHEAD rule 1002.f Date: 05/03/2026

Response: OTHER

Operator Comment: The well head will be cleaned later this week or next week: by 5/15/26

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 212603

Corrective Action: IMMEDIATE ACTION REQUIRED Comply with the fencing requirements per the 1002a rules FOR PROTECTION OF THE PUBLIC, LIVESTOCK AND WILDLIFE

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 05/01/2026

Operator Comment: Maralex removed all damaged fencing around both wells and replaced it with hardy calf wire panels, reinforced with more t-posts, on May 1, 2026.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 212604

Corrective Action: IMMEDIATE ACTION REQUIRED. Equipment must be returned to manufacturers safety specifications FOR SAFETY AND PROTECTION OF THE PUBLIC, LIVESTOCK AND WILDLIFE FOR ONGOING OPERATIONS

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 05/06/2026

Operator Comment: The belt guards have been rehung as of May 6, 2026. However, prior to this, the guards were set in such a way within the fencing that surrounded the pump jack that access to the belts was prevented, thus protecting wildlife, the public, etc.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 212605

Corrective Action: Stormwater management Erosion Control Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/03/2026

Response: OTHER

Operator Comment: Maralex is discussing with landowner how to coordinate irrigation efforts so that Maralex can put a culvert under the road. To my knowledge, this access issue is a recent problem as I am not aware of there ever being water in that field before now.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**5** CA# 212606

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 05/03/2026

Response: CA COMPLETED

Date of Completion: 04/29/2026

Operator Comment: This is a duplicative corrective action. Please see 212606.

ECMC Decision: \_\_\_\_\_

