

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2026

Submitted Date:

05/01/2026

Document Number:

701104728

FIELD INSPECTION FORM

Loc ID 335488 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298067	WELL	PR	01/31/2010	GW	045-17050	SAVAGE RWF 544-26	EG
298068	WELL	PR	02/26/2009	GW	045-17052	SAVAGE RWF 543-26	EG
298069	WELL	PR	12/31/2009	GW	045-17053	SAVAGE RWF 343-26	EG
298070	WELL	PR	12/31/2009	GW	045-17054	SAVAGE RWF 43-26	EG
298071	WELL	PR	01/31/2010	GW	045-17055	SAVAGE RWF 434-26	EG
298072	WELL	PR	01/31/2010	GW	045-17056	SAVAGE RWF 34-26	EG
298073	WELL	PR	01/31/2010	GW	045-17057	SAVAGE RWF 533-26	EG
298074	WELL	PR	12/31/2009	GW	045-17058	SAVAGE RMV 47-26	EG
298075	WELL	PR	01/11/2010	GW	045-17059	SAVAGE RWF 433-26	EG
298076	WELL	PR	01/31/2010	GW	045-17060	SAVAGE RWF 344-26	EG
298077	WELL	PR	10/01/2023	GW	045-17061	SAVAGE RWF 44-26	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Stain on tank and PRV.
Corrective Action: Clean staining from tank and PRV.
CA Date: 05/20/2026

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text" value="911"/>		
Corrective Action:	<input type="text"/>		Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	# 1		
Comment:	Dumpline has a cut or unlocked pad lock on shut in valve.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Stain on tank and PRV.				
Corrective Action:	Clean staining from tank and PRV.				Date: <u>05/20/2026</u>

Paint	
Condition	Adequate

Other (Content)	
Other (Capacity) 80 bbls	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: <u>298067</u>	Type: <u>WELL</u>	API Number: <u>045-17050</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298068</u>	Type: <u>WELL</u>	API Number: <u>045-17052</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298069</u>	Type: <u>WELL</u>	API Number: <u>045-17053</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298070</u>	Type: <u>WELL</u>	API Number: <u>045-17054</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298071</u>	Type: <u>WELL</u>	API Number: <u>045-17055</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298072</u>	Type: <u>WELL</u>	API Number: <u>045-17056</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298073</u>	Type: <u>WELL</u>	API Number: <u>045-17057</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298074</u>	Type: <u>WELL</u>	API Number: <u>045-17058</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298075</u>	Type: <u>WELL</u>	API Number: <u>045-17059</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298076</u>	Type: <u>WELL</u>	API Number: <u>045-17060</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>298077</u>	Type: <u>WELL</u>	API Number: <u>045-17061</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404644121	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535496
701104729	Flowline integrity inspection 701104728 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535493