

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2026

Submitted Date:

05/01/2026

Document Number:

715204424

**FIELD INSPECTION FORM**

Loc ID 324904 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC  
Address: 992 S 4TH AVE SUITE 100-461  
City: BRIGHTON State: CO Zip: 80601

**Findings:**

- 8 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Reed, Shawn	303-562-6530	shawn@sreedconsulting.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285624	WELL	SI	09/01/2025	GW	061-06793	FRAZEE B-14-2	PA

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a P&A Inspection  
Well was plugged. Operator has 30 days to remove equipment from location and begin final reclamation process

**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	Two track through pasture	
Corrective Action:			Date:

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type	TANK BATTERY	
	Comment:	Wire fence around water tank and VGS	
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 0		
	Comment:	Removed from well for plugging procedure	
Corrective Action:			Date:
Type: Vertical Separator	# 1		
	Comment:	VGS next to meter shed	
Corrective Action:	Operator has 30 days to remove equipment from location		Date: <u>06/01/2026</u>
Type: Gas Meter Run	# 1		
	Comment:	Meter run on SE corner of location	
Corrective Action:	Operator has 30 days to remove equipment from location		Date: <u>06/01/2026</u>
Type: Deadman # & Marked	# 4		
	Comment:		
Corrective Action:	Remove deadmen and markers		Date: <u>06/01/2026</u>

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		38.414670,-103.022040
	Comment:	Fiberglass open top water tank			
Corrective Action:	Operator has 30 days to remove tank from location				Date: <u>06/01/2026</u>

**Paint**

Condition:

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 285624 Type: WELL API Number: 061-06793 Status: SI Insp. Status: PA

**Cement**

Cement Contractor

Contractor Name: Bohler Well Service

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): 2075/1417/305

Cement Volume (sx): 180 SXS

Good Return During Job: YES

Cement Type: Class A

Comment: BOHLER WELL SERVICE. PUMPED 25 SXS CMT @ 2075'. PUMPED 50 SXS CMT @ 1417'. PUMPED 105 SXS CMT @ 305' W/CMT TO SFC.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404643757	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535048">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535048</a>
715204450	plugging equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535045">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7535045</a>