

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2026

Submitted Date:

05/01/2026

Document Number:

719001938

FIELD INSPECTION FORM

Loc ID: 325560 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		mollieo@maralexinc.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	
,		pbechtolt@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215004	WELL	PR	12/01/2025	DM	067-06609	HEIKKINEN 1-10	PR

General Comment:

Inspection Report Summary
On 4/30/26 | Inspector Charles Garcia conducted an on-site inspection.
Location: HEIKKINEN 1-10
Operator: MARALEX RESOURCES INC
API#: 067-06609
County: LaPlata
All prior CA's still stand

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-563-4000 911 EMERGENCY		
Corrective Action:			Date:
Good Housekeeping:			
Type	WEEDS		
Comment:	OVERGROWN VEGATATION ON LOCATION SEE LOCATION PICTURES		
Corrective Action:	Control weeds and undesirable vegetation per Rule 606		Date: 05/07/2026
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	CATTLE PANELS		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment: METER HOUSES			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment: TELEMETRY EQUIPMENT			
Corrective Action:			Date:
Type: Other	# 1		
Comment: WELLHEAD			
Corrective Action:			Date:

Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215004 Type: WELL API Number: 067-06609 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 12/08/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
OVERGROWN VEGATATION ON LOCATION SEE LOCATION PICTURES Control weeds and undesirable vegetation per Rule 606	garciacr1	05/01/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404643054	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534535
719001939	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534533