

FORM INSP Rev X/20	State of Colorado Energy and Carbon Management Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109	 	Inspection Date: 05/08/2026 Submitted Date: 05/08/2026 Document Number: 719001972
FIELD INSPECTION FORM			

Loc ID: 325048 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments

2 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213870	WELL	PR	03/16/1989	GW	067-05139	SNOOK A 1	PR

General Comment:

[Inspection Report Summary](#)
 On 5/8/26 I Inspector Charles Garcia conducted an on-site inspection.
 Location: WIRT D 1
 Operator: Simcoe LLC
 API#: 067-05139
 County: LaPlata
 All prior CA's still stand

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN AT ENTRANCE		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PRODUCED WATER TANK SIGN LAYING ON GROUND AND SUN DAMAGED SEE LOCATION PICTURES		
Corrective Action:	Install sign or correct sign per rule 605	Date:	05/15/2026

Emergency Contact Number:			
Comment:	Contact # 970-247-6916 Emergency #911		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	WELLHEAD		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	METER HOUSES CALIBRATION IN COMPLIANCE		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		
Comment: 95 BBL TANK HAS NO PAINT SEE LOCATION PICTURES					
Corrective Action: 600.b MAINTAIN TANK PAINT					Date: 05/22/2026

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
2 CA,S TANK PAINT AND TANK SIGN SEE LOCATION PICTURES	garciacr1	05/08/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
719001973	LOCATION PICTURES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7543423