

Inspection Photos

04/30/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335067

Inspection Doc: 719201111

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 1: Photos showing an overview of separator and tank equipment at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 2: Photos showing an overview of the wellhead area at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 3: Photos showing an example of wellhead signage that is faded and becoming difficult to read. Maintenance is recommended.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 4: Photos showing an overview of the northern interim area. Perennial, desirable and uniform vegetation is well established throughout.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 5: Photos showing the southeastern interim area is overtaken with cheatgrass. Redstem fillaree, prickly Russian thistle and bulbous bluegrass are present along the margins of the working pad surface. Weed maintenance is required; comply with Rules 606.c. and 1003.f.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 6: Redstem fillaree, prickly Russian thistle and bulbous bluegrass are present along the margins of the working pad surface.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 7: Bulbous bluegrass, a List C noxious weed species, is present throughout the interim areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 8: Photos showing deep vehicle tracking that is occurring throughout the working pad surface. Gravel appears to be sparse throughout. Maintenance is required; comply with Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335067



Photo 9: Photos showing an example of the nearby reference area, located directly east of the pad. The reference area is composed of mature big sagebrush and pinyon-juniper trees. Cheatgrass is present in the understory.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources