

Inspection Photos

04/30/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335159

Inspection Doc: 719201113

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335159



Photo 1: This is a two-tier location. Photos showing an overview of separator and tank equipment at the location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335159



Photo 2: This is a two-tier location. Photos showing an overview of the wellhead area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335159



Photo 3: Photos showing an overview of the northern interim area. The interim areas are overtaken by cheatgrass, a List C noxious weed, and weedy annual mustards. Little to no desirable vegetation is present. Additional reclamation efforts are required to establish desirable, perennial and uniform vegetation of at least eighty (80) percent cover of the nearby reference area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335159



Photo 4: Photos showing an overview of the southern interim area. The interim areas are overtaken by cheatgrass, a List C noxious weed, and weedy annual mustards. Little to no desirable vegetation is present. Additional reclamation efforts are required to establish desirable, perennial and uniform vegetation of at least eighty (80) percent cover of the nearby reference area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335159



Photo 5: Photos showing an overview of the southern interim area. The interim areas are overtaken by cheatgrass, a List C noxious weed, and weedy annual mustards. The yellow arrow points to scarlet globemallow (a desirable perennial forb) individuals that are scattered throughout. Additional reclamation efforts are required to establish desirable, perennial and uniform vegetation of at least eighty (80) percent cover of the nearby reference area.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335159



Photo 6: Photos showing the nearby reference area, directly east of the location. Cheatgrass is present in the understory; however, the area is a big sagebrush flat, with secondary to tertiary amounts of pinyon and juniper trees.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335159



Photo 7: Photos showing holes in the black geotextile liner of the secondary containment system. Maintenance is required; comply with Rule 603.o.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources