

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2026

Submitted Date:

05/05/2026

Document Number:

701104744

FIELD INSPECTION FORM

Loc ID 334733 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290043	WELL	PR	05/01/2025	GW	045-13961	MAP LLC 11-14 (PK11)	EG
292399	WELL	PR	05/01/2025	GW	045-14721	MAP LLC 11-11BB (PK11)	EG
292400	WELL	PR	05/01/2025	GW	045-14720	MAP LLC 11-13BB (PK11)	EG
293124	WELL	PR	05/01/2025	GW	045-14899	MAP LLC 11-14BB (PK11)	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Follow up to 1/28/2026 inspection # 701104483
Tank label was replaced.
Paint deterioration and areas of rust on tanks.
Additional torn and damaged labels found on 4/29/2026.
Install sign to comply with Rule 605.h.
CA Date 07/3/2026

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Tank label was replaced. Additional torn and damaged labels found on 4/29/2026.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	07/03/2026

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	<input type="text"/>
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

Inspected Facilities

Facility ID: <u>290043</u>	Type: <u>WELL</u>	API Number: <u>045-13961</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>292399</u>	Type: <u>WELL</u>	API Number: <u>045-14721</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>292400</u>	Type: <u>WELL</u>	API Number: <u>045-14720</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>293124</u>	Type: <u>WELL</u>	API Number: <u>045-14899</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404647909	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7539147
701104745	Flowline integrity inspection 701104744 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7539142