

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/05/2026

Submitted Date:

05/05/2026

Document Number:

719001953

**FIELD INSPECTION FORM**

Loc ID: 333963 Inspector Name: GARCIA, CHARLES On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 9 Number of Comments  
 2 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 ECMC Operator Number: 53255  
 Name of Operator: MARALEX RESOURCES INC  
 Address: P O BOX 338  
 City: IGNACIO State: CO Zip: 81137

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		pbechtolt@maralexinc.com	
		mollieo@maralexinc.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276035	WELL	PR	10/01/2025	CBM	067-09016	KEEGAN PATRICK 33-7-11 2A	PR
298720	WELL	PR	08/01/2025	CBM	067-09631	KEEGAN PATRICK 33-7-11 3C	PR

**General Comment:**  
[Inspection Report Summary](#)  
 On 5/5/26 I Inspector Charles Garcia conducted an on-site inspection.  
 Location: KEEGAN PATRICK 33-7-11 2A, KEEGAN PATRICK 33-7-11 3C  
 OPERATOR: MARALEX RESOURCES INC  
 API#: 067-09016  
 API#:067-09631  
 County: LaPlata  
 All prior CA's still stand

Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	WELL SIGN		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-563-4000 911 EMERGENCY		Date:
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	OVERGROWN VEGATATION ON LOCATION SEE LOCATION PICTURES		
Corrective Action:	Control weeds and undesirable vegetation per Rule 606".		Date: 05/12/2026
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	METER HOUSES		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 2		

Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	WELHEADS		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:	PUMP JACK ON THE 3C HAD A OIL LEAK AT SOME POINT AND FLOWED OVER ON TO SIDE OF PUMP JACK IMPACTING SOIL SEE LOCATION PICTURES		
Corrective Action:	MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND PUMPJACK rule 1002.f		Date: 05/08/2026

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 276035 Type: WELL API Number: 067-09016 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**BradenHead**

Date of Last Brhd Test: 10/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

Facility ID: 298720 Type: WELL API Number: 067-09631 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**BradenHead**

Date of Last Brhd Test: 10/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:		
Corrective Action:		Date: <span style="border-bottom: 1px solid black; display: inline-block; width: 50px;"></span>

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
PUMP JACK ON THE 3C HAD A OIL LEAK AT SOME POINT AND FLOWED OVER ON TC SIDE OF PUMP JACK IMPACTING SOIL SEE LOCATION PICTURES MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND PUMPJACK rule 1002.f OVERGROWN VEGATATION ON LOCATION SEE LOCATION PICTURES Control weeds and undesirable vegetation per Rule 606".	garciacr1	05/05/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404647936	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7539181">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7539181</a>
719001954	LOCATION PICTURES	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7539178">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7539178</a>