

Inspection Photos

05/08/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335202

Inspection Doc: 719201127

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 1: This is a two-tiered location. Photos showing tank and separator equipment.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 2: This is a two-tiered location. Photos showing the wellhead area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 3: A tree has fallen and is partially lying on the fence directly behind production equipment; removal is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 4: Photo showing debris/trash near the gate leading to the wellhead area that requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 5: Photos showing the southern and western interim areas, respectively. Interim areas are composed of smooth brome, western wheatgrass and other mixed pasture grasses.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 6: Photos showing an example of claspings pepperweed and bulbous bluegrass, an undesirable plant species and List C noxious weed, that are present throughout the interim areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 7: Photos showing an example of kochia and prickly Russian thistle present along the edges of the pad and an example of plant composition at the location, respectively. Bulbous bluegrass, cheatgrass, kochia, and redstem fillaree is present throughout the interim areas.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 8: Photos showing an API # that is missing a numeral (left) and a wellhead sign that does not have an API # listed. Maintenance is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335202



Photo 9: Vehicle tracking and rutting is present near the production equipment area. Maintenance is required pursuant to Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources