


**Inspection Photos**  
**Location Name: Simcoe Craig #2**  
**Location ID: API 05-067-08342**



**1. Well sign inside cattle panel fence by pad entrance by production equipment.**

**2. Well location and pad overview from pad entrance. Sign is visible on left side.**

Inspection Photos  
Location Name: Simcoe Craig #2  
Location ID: API 05-067-08342



**3. Wellhead and pumpjack. There is stained gravel near the wellhead.**

**4. Wellhead. Stained gravel surrounding wellhead appears oily. Absorbent pads wrapped around stuffing box. View looking N.**

**Inspection Photos**  
**Location Name: Simcoe Craig #2**  
**Location ID: API 05-067-08342**



**5. Wellhead. Oil staining visible on gravel surrounding wellhead. View looking E.**



**6. Wellhead and pumpjack with gas prime mover. Was operating during inspection. Cattle panel barrier and solar telemetry.**

Inspection Photos  
Location Name: Simcoe Craig #2  
Location ID: API 05-067-08342



**7. Wellhead, pump jack and prime mover.**

**8. Lube oil container of leak protection. Leak protection capacity is adequate. No stains observed below tank.**

Inspection Photos  
Location Name: Simcoe Craig #2  
Location ID: API 05-067-08342



**9. Solar telemetry for well controls. Muffler for prime mover on gravel.**

**10. Partially buried steel tank inside of containment. 95 bbl PBV, no contents, capacity or NFPA information observed. View looking NW.**

## Inspection Photos

Location Name: Simcoe Craig #2

Location ID: API 05-067-08342




11. From left to right looking north: PBV tank, flowlines, vertical heated separator, production flowlines, meter run. Meter calibration card is inside meter run shed in plastic sleeve. Date is 7/14/25. Rig anchor lacks marker. View looking N.



12. Pad overview. Rig anchor lacks proper marker. Only 18" cable stub. Irrigation ditch and active pasture on right of fence. View looking N along E edge of pad.

**Inspection Photos**  
**Location Name: Simcoe Craig #2**  
**Location ID: API 05-067-08342**



**13. Pad overview and tilled cropland outside of fence on left. Rig anchor is marked.**