

# Inspection Photos

05/08/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335245

Inspection Doc: 719201131

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335245



**Photo 1:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335245



**Photo 2:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335245



**Photo 3:** Photos showing an overview of the eastern and western interim areas, respectively. Redstem fillaree, a List C noxious weed, is dominant in some portions of the western interim area.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335245



**Photo 4:** Photos showing examples of whitetop, a List B noxious weed, and kochia, an undesirable plant species, are present along wattles on the eastern cut slope. Weed management is required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335245



**Photo 5:** Photos showing additional examples of bulbous bluegrass and portions of the northern interim area that are dominated by noxious weeds and undesirable plant species. Weed management is required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335245



**Photo 6:** Photo showing eastern cut slopes are well vegetated. Overall, interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335245



**Photo 7:** Photo showing a small hole is present in a patch at the tank's secondary containment black geotextile liner. Maintenance is required.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335245



**Photo 8:** The northwestern sediment trap is in functioning condition at the time of inspection but appears to have reached capacity and may need maintenance soon.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources