

# INSPECTION PHOTOS

Well: BUSTER 13-1

API #: 05-071-08986

INSPECTION DOC #: 716302344

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 5/13/2026

County: Las Animas



PHOTO 2: WELL SIGN



Network: May 13, 2026 at 11:13:53 AM MDT  
Local: May 13, 2026 at 11:13:53 AM MDT  
+37.287301, -104.738762

PHOTO 3: LOCATION.



Network: May 13, 2026 at 11:28:40 AM MDT  
Local: May 13, 2026 at 11:28:40 AM MDT  
+37.287094, -104.738483  
11978 S

PHOTO 4: WELLHEAD AND EQUIPMENT.



Network: May 13, 2026 at 11:17:12 AM MDT  
Local: May 13, 2026 at 11:17:12 AM MDT  
+37.286960, -104.738495  
142° SE

**PHOTO 5: AREA OF IMPACTED SOIL NEAR PRIME MOVER SKID. AT TIME OF INSPECTION THIS EQUIPMENT IS NOT IN OPERATION HOWEVER IT APPEARS TO HAVE SIGNIFICANT OIL LEAKS THAT SHOULD BE REPAIR PRIOR TO PUTTING EQUIPMENT BACK IN USE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D CA DATE 6/13/2026.**



**PHOTO 6: AREA OF IMPACTED SOIL NEAR PRIME MOVER SKID. AT TIME OF INSPECTION THIS EQUIPMENT IS NOT IN OPERATION HOWEVER IT APPEARS TO HAVE SIGNIFICANT OIL LEAKS THAT SHOULD BE REPAIR PRIOR TO PUTTING EQUIPMENT BACK IN USE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D CA DATE 6/13/2026.**



Network: May 13, 2026 at 11:17:40 AM MDT  
Local: May 13, 2026 at 11:17:40 AM MDT  
+37.286876, -104.738419  
34.9° NW

**PHOTO 7: AREA OF IMPACTED SOIL NEAR PRIME MOVER SKID. AT TIME OF INSPECTION THIS EQUIPMENT IS NOT IN OPERATION HOWEVER IT APPEARS TO HAVE SIGNIFICANT OIL LEAKS THAT SHOULD BE REPAIR PRIOR TO PUTTING EQUIPMENT BACK IN USE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D CA DATE 6/13/2026.**



Network: May 13, 2026 at 11:18:44 AM MDT  
Local: May 13, 2026 at 11:18:44 AM MDT  
+37.286838, -104.738467  
201° W

**PHOTO 8: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. AT TIME OF INSPECTION THIS EQUIPMENT IS NOT IN OPERATION HOWEVER IT APPEARS TO HAVE SIGNIFICANT OIL LEAKS THAT SHOULD BE REPAIR PRIOR TO PUTTING EQUIPMENT BACK IN USE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D CA DATE 6/13/2026.**



Network: May 13, 2026 at 11:19:09 AM MDT  
Local: May 13, 2026 at 11:19:09 AM MDT  
+37.286889, -104.738542  
79° F

**PHOTO 9: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. AT TIME OF INSPECTION THIS EQUIPMENT IS NOT IN OPERATION HOWEVER IT APPEARS TO HAVE SIGNIFICANT OIL LEAKS THAT SHOULD BE REPAIR PRIOR TO PUTTING EQUIPMENT BACK IN USE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D CA DATE 6/13/2026.**



Network: May 13, 2026 at 11:15:27 AM MDT  
Local: May 13, 2026 at 11:15:27 AM MDT  
+37.287235,-104.738643  
296° W

PHOTO 10: CULVER AT ENTRANCE OF LOCATION IS PLUGGED. **CLEAN CULVER PER RULE 1002. CA DATE 6/13/2026.**



**PHOTO 11: RECENT RECLIMATION AREA DISTURBANCE DOES NOT APPEAR TO HAVE BEEN RESEEDED. SEED DISTURBED AREA PER RULE 1003. CA DATE 7/15/2026.**