

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2026

Submitted Date:

05/13/2026

Document Number:

713302661

**FIELD INSPECTION FORM**

Loc ID: 318429    Inspector Name: Kester, Michael    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
 Name of Operator: KP KAUFFMAN COMPANY INC  
 Address: 1700 LINCOLN ST STE 4550  
 City: DENVER    State: CO    Zip: 80203

**Findings:**

6    Number of Comments  
 0    Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>
Silver, Randy	720-827-6688	randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241279	WELL	TA	10/13/2015	OW	123-09067	UPRR 43 PAN AM B 8	TA

**General Comment:**

[well site inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	NO Access		
Corrective ActionL		Date:	

Overall Good:

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 90%;" type="text"/>
Corrective Action:	<input style="width: 90%;" type="text"/>
	Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 241279 Type: WELL API Number: 123-09067 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: wells production equipment/facility at  
 UPRR 43 PanAm B7 / 123-09018 - 318400  
 Form 6 on file, well P&A 10-16-2023, doc 403547691  
 removed and remediation in process  
 form 27, 404529438 4-22-2026

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/04/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_  
 End Surf Csg Pressure: 0

Comment: [Submit report](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
<a href="#">Audit of scout card and related documents</a>  UPRR 43 PanAm B8, flowline to production equipment/facility Spindle Consolidation Facility #1 shared well pad with  UPRR 43 PanAm B7 / 123-09018 - 318400 Form 6 on file, well P&A 10-16-2023, doc 403547691 removed and remediation in process form 27, 404529438 4-22-2026  All wells on this gathering system P&A, except UPRR 43 PanAm B8 and production facility removed  This inspection does not nullify any orders or NOAV from the ECMC	kesterm	05/13/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713302662	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7548575">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7548575</a>