

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 05-067-08388



1. Sign for Simon Land and Cattle 15U-2R 2 well head on fence.

2. Sign for Simon Water Disposal Well #1 just inside front gate to location. Disposal well facilities not inspected.

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 05-067-08388



3. Electric drive linear rod pump on top of 15U-2R wellhead behind cattle panel. Pump was operating at time of inspection.

4. No stained soil observed at 15U-2R wellhead.

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 05-067-08388



5. NW rig anchor with down anchor marker.



6. Valve on 6" pipeline for offsite gathering or produced water for injection well. Chemical treatment container on top of spill release with solar telemetry. Has manufacturer labelling.

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2
Location ID: 333594; API 05-067-08388



7. Manufacturer's labelling on chemical treatment container.

8. Unnecessary equipment. Appears to be 300 gal (est) lube oil tank with gravity fed unloading nozzle for filling smaller containers. Labeled "Honstein Oil. 505-632-5730. EL MAR LOW ASH GEO SAE 15W-40". Secondary containment has wildlife mesh (chicken wire) and is empty. Site glass indicates tank is empty. Not needed for gas well production equipment. Does not appear to be in use. Vertical heated separator in background.

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 333594; API 05-067-08388



9. 15U-2R 2 production equipment behind cattle panel fence. Vertical heated separator and meter run. 4" production flowlines connecting equipment.



10. Solar telemetry and valve riser behind cattle panel.

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 333594; API 05-067-08388



11. Steel PBV tank, volume unknown, not properly labeled/signed. Yellow arrow indicates sign that has fallen over, is not legible on face-down side. Located in NW corner of pad. Storage container and other equipment on other side of chain link fence presumably belong to surface owner not part of oil and gas operations.

12. Additional photo showing unlabeled PBV produced water tank and secondary containment. Tank and secondary containment appear to be in adequate condition.

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 333594; API 05-067-08388



13. Underground flow line valve access box with T handle.



14. Three underground flow line valve access boxes with T handles.

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 05-067-08388



15. Location overview photo. 15E-2R 2 wellhead in middle of photo. Disposal well shelter to left. Disposal well equipment in background.



16. Location perimeter chain link fence on south side of location looking east.

Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 333594; API 05-067-08388



Inspection Photos

Location Name: Simcoe – Simon Land and Cattle 15U-2R 2

Location ID: 333594; API 05-067-08388



27. Pad margin along northern fence looking east. Tanks are associated with injection well facilities.