

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2026

Submitted Date:

05/08/2026

Document Number:

712300314

FIELD INSPECTION FORM

Loc ID: 434014 Inspector Name: Maxwell, Logan On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10805
Name of Operator: FULCRUM ENERGY OPERATING LLC
Address: 240 SAINT PAUL STREET SUITE 502
City: DENVER State: CO Zip: 80206

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		inspections@fulcrumeo.com	
		annalee@fulcrumef.com	
		rikki.ross@fulcrumeo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434014	LOCATION	AC			-	HEBRON CENTRAL FACILITY 434014	RI

General Comment:

On 4/22/2026, Acting Reclamation Supervisor Trujillo and Northwest Reclamation Specialist Maxwell conducted an inspection at Fulcrum Energy's Hebron Central Facility, ID: 434014 in Jackson County, CO.

The following compliance issues remain:

- Broken glass near shed
- Weeds will have to be evaluated at a future inspection

Refer to the "Location," and "Reclamation," sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective actions from previous inspections that have not been addressed remain applicable. Any new corrective actions without corrective action dates, requires that the Operator comply with the Rules as soon as possible or when environmental conditions permit. Location will remain out of compliance until corrective action(s) has (have) been resolved and a follow up inspection will be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.

Location			
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
Good Housekeeping:			
Type	OTHER		
Comment:	<p>It was observed in the previous inspection that vegetation growth was abundant within secondary containment structures surrounding the equipment and along the berms of secondary containment. FIRR #404315754 was submitted stating this was resolved.</p> <p>Vegetation has removed surrounding the equipment and within secondary containment. This CA is resolved.</p>		
Corrective Action:			Date: _____
Type	WEEDS		
Comment:	<p>It was observed in the previous inspection that Undesirable plant species, such as Cheatgrass, established along portions of the perimeter berms. FIRR #404315754 was submitted stating this was resolved.</p> <p>Staff will have to determine at a future date if cheatgrass or other weeds have re-established, as soon as environmental conditions allow. This CA date remains open until a futue inspection.</p>		
Corrective Action:	Comply with Rule 606.c.		Date: _____
Type	TRASH		
Comment:	<p>It was observed in the previous inspection that trash was found inside the building. FIRR #404315754 was submitted stating this was resolved.</p> <p>It was observed in this inspection that the glass from the building door shattered. Staff did not go into the building, due to broken glass surrounding the door. A new CA date is included for the broken glass on the door.</p>		
Corrective Action:	Comply with Rule 606.d.- remove broken glass.		Date: <u>05/22/2026</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Comment:	<p>It was observed in the previous inspection that stained soils were evident across the Location, primarily observed inside the shed. FIRR #404315754 was submitted stating this was resolved.</p> <p>Although staff did not enter the shed, no stained soils were observed across the Location. This CA is resolved.</p>		
Corrective Action:			Date: _____
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	<p>It was observed in the previous inspection that the fencing at both entrances of the Location were not been maintained and were no longer functioning to keep cattle out. FIRR #404315754 was submitted stating this was resolved.</p> <p>It was observed in this inspection that the fencing was fixed. This CA is resolved.</p>		
Corrective Action:			Date: _____

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 434014 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: At the time of this inspection, not stormwater issues were observed.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404652959	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7543899
712300316	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7543880