

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2026

Submitted Date:

05/15/2026

Document Number:

708909170

**FIELD INSPECTION FORM**

Loc ID 335131 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Findings:**

22 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
QB ENERGY		ecmc.inspections@qb-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269125	WELL	PR	09/01/2004	GW	045-09323	PUCKETT 33C-25	SI
293505	WELL	PR	03/01/2023	GW	045-15016	PUCKETT 33C2-25D	SI
293506	WELL	PR	12/31/2008	GW	045-15017	PUCKETT 33B-25D	SI
293507	WELL	PR	12/31/2008	GW	045-15018	PUCKETT 33A-25D	SI
293508	WELL	PR	12/31/2008	GW	045-15019	PUCKETT 33D-25D	SI

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
	Type BATTERY		
Comment:			
Corrective Action:			Date:
	Type OTHER		
Comment:	Sign near entrance to location		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment: 911/970-285-2615		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:			Date:
	Type SEPARATOR		
Comment:	Barbed wire fence		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Liquid nitrogen tank - pipe rail fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	PUCKETT 33C2-25D well has Taylor plug located on bradenhead Remaining 4 wells have no form of pressure monitoring equipment located on bradenheads		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 269125 Type: WELL API Number: 045-09323 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut In

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293505 Type: WELL API Number: 045-15016 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut In

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293506 Type: WELL API Number: 045-15017 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut In

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293507 Type: WELL API Number: 045-15018 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut In

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293508 Type: WELL API Number: 045-15019 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Shut In

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
Berms						
		Gravel				Sparse to none
		Compaction				Light compaction in some sections
		Check Dams				
		Berms				
		Culverts				
		Ditches				
Compaction						Small amount of light compaction
		Drains				
Gravel						Sparse to none in most areas
		Rip Rap				
		Retention Ponds				

Comment:

Corrective Action:

Date:

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a>                      On 05/13/2026 at approximately 14:35 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at QB ENERGY OPERATING LLC PUCKETT 33C-25 (MESA 18) Pad                      Location # 335131 in Garfield County Colorado.                      Please refer to inspection/audit 708908094 conducted on 12/22/2025 &amp; inspection/audit 708908882 conducted on 04/06/2026, previous corrective actions have been completed.                      Location is within High Priority/Density/Black Bear Habitat areas.                      While there, I observed normal production operations.</p> <p>This is a summary of inspection/audit report.</p>	smelserw	05/15/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708909171	Inspection/Audit 708909170 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550171">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550171</a>
708909172	Inspection/Audit 708909170 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550172">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550172</a>