

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2026

Submitted Date:

05/17/2026

Document Number:

708909176

**FIELD INSPECTION FORM**

Loc ID 336056 Inspector Name: Smelser, Wayne On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: CHEVRON USA INC  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 15 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
CHEVRON USA INC		atlx@chevron.com	
CHEVRON USA INC		rbucogccinspectionreports@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
493607	WELL	DG	05/09/2026		045-24614	SKR 698-10BV-770	DG

**General Comment:**

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Rig sign at intersection of Roan Creek Rd & start of Clear Creek Rd		
Corrective Action:			Date:
Type	OTHER		
Comment:	Rig sign at intersection of Clear Creek Rd & lease road		
Corrective Action:			Date:
Type	OTHER		
Comment:	Location sign at intersection of Clear Creek RD & start of lease road		
Corrective Action:			Date:
Type	OTHER		
Comment:	Location sign on spur road near entrance to location		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	911/1-877-257-6007	
Corrective Action:		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Drilling rig		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Pump truck		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Cement truck		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 493607 Type: WELL API Number: 045-24614 Status: DG Insp. Status: DG

**Cement**

Cement Contractor

Contractor Name: Haliburton

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment: [FORM 42 NOTICE TO RUN AND CEMENT CASING document # 404608177](#)  
[Observed rig crew preparing to run surface casing](#)

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
				Covering Materials		Plastic wrap/plastic sheeting
Ditches						
Retention Ponds						
		Gravel				Sparse to none
				Material Handling And Spill Prevention		Chemical containments
Drains						
Compaction						
		Compaction				
		Ditches				
Berms						
Gravel						Sparse to none in most areas

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a>                      On 05/12/2026 at approximately 09:30 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection/audit at CHEVRON USA INC SKR 698-10-BV Pad Location # 336056 in Garfield County Colorado.                      Location is within High Priority/Density/NSO/Black Bear Habitat areas.                      Location is approximately 46 yards from Deer Park Gulch.                      While there, I observed drilling operations on the SKR 698-10BV-770 well.</p> <p>This is a summary of inspection/audit report.</p>	smelserw	05/17/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708909177	Inspection/Audit 708909176 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550238">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550238</a>