

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2026

Submitted Date:

05/17/2026

Document Number:

708909178

FIELD INSPECTION FORM

Loc ID 324306 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: CHEVRON USA INC
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
CHEVRON USA INC		rbucogccinspectionreports@chevron.com	
CHEVRON USA INC		atlx@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277537	WELL	PR	03/01/2019	GW	045-10714	SKINNER RIDGE 698-12-1	PR

General Comment:

[This is a Field Inspection/Audit of the scout card, related documents and the location.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No signage at battery		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chamical tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign on lease road near entrance to location		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/1-877-257-6007		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe rail fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Other	# 2		
Comment:	Fire extinguishers		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	Marked		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 277537 Type: WELL API Number: 045-10714 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Check Dams						
Gravel						Sparse to none in most areas
		Culverts				
				Material Handling And Spill Prevention		Chemical tank containment
		Gravel				Sparse to none
Compaction						Small amount of light compaction
Berms						
		Compaction				Small amount of light compaction

Comment: Chemical tank containment approximately 3/8 full of fluid/BMP may need maintenance in the near future

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 05/12/2026 at approximately 11:02 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection/audit at CHEVRON USA INC SKINNER RIDGE 698-12-1 Location # 324306 in Garfield County Colorado. Please refer to inspection/audit 713400686 conducted on 02/04/2025, previous corrective action has been completed. Location is within High Priority/Density/NSO/Black Bear Habitat areas. Location is approximately 12 yards from Deer Park Gulch. While there, I observed normal production operations.</p> <p>Comments -</p> <p>Stormwater - Chemical tank containment approximately 3/8 full of fluid/BMP may need maintenance in the near future.</p> <p>This is a summary of inspection/audit report.</p>	smelserw	05/17/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708909179	Inspection/Audit 708909178 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550241
708909180	Inspection/Audit 708909178 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550242