

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2026

Submitted Date:

05/11/2026

Document Number:

720800454

FIELD INSPECTION FORM

Loc ID 331151 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 83130
Name of Operator: STRACHAN EXPLORATION INC
Address: 992 S 4TH AVE SUITE 100-461
City: BRIGHTON State: CO Zip: 80601

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Harms, Jason	303-330-1921	jason@strachanexploration.com	
Reed, Shawn		Shawn@strachanexploration.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258930	WELL	PR	01/01/2022	GW	123-20234	FEDERAL TOUCAN 28-14	PR

General Comment:

This is a Well Site Field Compliance Audit of the Scout Card, Related Documents and the Location. Any Corrective Actions to FIR 718300042 dated 07.23.2025 that have not been address are still applicable.

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			
Good Housekeeping:			
Type	DEBRIS		
Comment:	Tumbleweeds at Well site; see photos		
Corrective Action:	Comply with Rule 606		Date: <u>05/29/2026</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Barbed wire fencing has been installed around the well and pumping unit; however, fencing requires maintenance - Access gate was open and the southern stretch of fencing was down at the time of inspection. Livestock footprints and manure were observed throughout the location both inside and outside the fenced area (Photos 2-7). Fencing is no longer adequate/effective at excluding entry of people, livestock or wildlife at time of inspection		
Corrective Action:	Operator shall immediately install, repair and maintain best management practices to protect the environment, public health, safety and welfare and the environment as required by Rule 913.b.(5)B.i and ECOM Guidance 913.b.(5)B i-v which requires fencing used be appropriate to site conditions, ie: nearby residences, depth of excavation, presence of ground or surface water, livestock, wind, etc.		Date: <u>05/29/2026</u>
Equipment:			
Type: Bradenhead # 1			corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack # 1			
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked # 4			
Comment:	Southwest Deadman Anchor not marked; see photos		
Corrective Action:			Date:
Type: Prime Mover # 1			

Comment: Gas Engine		
Corrective Action:		Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 258930 Type: WELL API Number: 123-20234 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404654119	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7544965
720800455	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7544963