

# Inspection Photos

05/14/2026

Operator: Chevron USA Inc #16700

Location ID: 315050

Inspection Doc: 719201157

Rio Blanco County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 315050

5/14/2026 12:22 PM  
358° N



5/14/2026 12:22 PM  
180° S



**Photo 1:** Photo left looking north at the location from the toe of the reclaim. Photo right looking south at the access road that runs along the toe of the location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 315050



**Photo 2:** Photos showing an overview of the location looking north and south, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 315050



**Photo 3:** Photos showing an overview of the location looking east and west, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 315050



**Photo 4:** Photos showing that desirable, perennial vegetation on some portions of the location have not yet reached uniformity.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 315050



**Photo 5:** Photos showing some stormwater controls need maintenance (yellow arrows); some wattles are overtopped with sediment and some have erosion/soil piping occurring underneath.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 315050



**Photo 6:** Photos showing examples of twine trash that is scattered throughout and downed fencing and barbed wire on the northern portion of the location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 315050



**Photo 7:** Photos showing the reclaimed utility line ROW located directly south of the location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: Chevron USA Inc #16700

Location ID: 315050



**Photo 8:** Photos showing tertiary amounts of bulbous bluegrass and a weedy mustard (*Alyssum* sp.), both undesirable plant species, that is present at the intersection of the utility ROW and County Road 9. Weed control is not required at this time; however, ongoing weed maintenance and monitoring is necessary until the location receives a passing final reclamation inspection.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources