

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2026

Submitted Date:

05/12/2026

Document Number:

697602633

FIELD INSPECTION FORM

Loc ID: 490250 Inspector Name: Ahmadian, Alexander On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
		Jaron_Bartoszek@oxy.com	
Robinson, Taylor		taylor.robinson@state.co.us	
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
494039	SPILL OR RELEASE	AC	05/11/2026		-	FERN HZ Facility	EI

General Comment:

This is the initial environmental inspection in response to the Weld OEM Spill Report Form to determine progress on Spill ID 494039. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: Yes

Comment: ECMC staff observed spill within secondary containment.

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: _____					
Corrective Action: _____					Date: _____

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Adequate				
Corrective Action: _____				Date: _____

Venting:

Yes/No	
Comment:	
Corrective Action:	Date: _____

Flaring:

Type	
Comment:	
Corrective Action:	Date: _____

Inspected Facilities

Facility ID: 494039 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER Estimated Spill Volume: _____

Comment: Produced water and condensate spill. ECMC was notified by the Operator through the Weld OEM Spill Report Form. Spill is within secondary containment.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. Date: 08/24/2026

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Operator has submitted Form 19 Document #404651723 to address the spill.

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404656634	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7547018
697602634	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7547015