

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/04/2026

Submitted Date:

05/12/2026

Document Number:

701104765

FIELD INSPECTION FORM

Loc ID 335587 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269644	WELL	PR	09/18/2006	GW	045-09389	CHEVRON GM 33-17	EG
287806	WELL	PR	06/26/2007	GW	045-13078	CHEVRON GM 433-17	EG
287807	WELL	PR	11/13/2006	GW	045-13077	CHEVRON GM 533-17	EG
287808	WELL	PR	11/13/2006	GW	045-13076	CHEVRON GM 432-17	EG
287809	WELL	PR	11/13/2006	GW	045-13075	CHEVRON GM 333-17	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
 Single unit separator glycol vessel paint is deteriorated with areas of rust corrosion.
 Lines and fittings at separators have deteriorated paint with areas of rust corrosion.
 4 ball valves on the quad separator have no plugs. 3 ball valves on separator glycol vessels have no plugs.
 Comply with Rule 603.i..
 CA Date 05/29/2026

Location

Lease Road:

	Type Access		
comment:			
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	
	Type BATTERY		
Comment:			
Corrective Action:		Date:	
	Type TANK LABELS/PLACARDS		
Comment:	See inspection # 708908844 Incorrect tank capacity on 210 bbl tank label.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

	#		corrective date
Type: Flow Line	# 3		
Comment:	Tank load lines in tank berm is unpainted or deteriorated paint with areas of rust. Unpainted or deteriorated paint dump line and fittings with areas of rust corrosion. Sells manifold line in front of separators is partially buried, and paint is deteriorated with areas of rust corrosion.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 5		
Comment:	Single unit separator glycol vessel paint is deteriorated with areas of rust corrosion. Lines and fittings at separators have deteriorated paint with areas of rust corrosion. 4 ball valves on the quad separator have no plugs. 3 ball valves on separator glycol vessels have no plugs.		
Corrective Action:	Comply with Rule 603.i..	Date:	05/29/2026

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,

Comment:		Tank's paint is deteriorated with areas of rust corrosion.				Date:	
Corrective Action:						Date:	
Paint							
Condition	Inadequate						
Other (Content)							
Other (Capacity)		210 bbls					
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	300 BBLs	STEEL AST				
Comment:		Tank's paint is deteriorated with areas of rust corrosion.				Date:	
Corrective Action:						Date:	
Paint							
Condition	Inadequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:						Date:	
Corrective Action:						Date:	
Venting:							
Yes/No							
Comment:						Date:	
Corrective Action:						Date:	
Flaring:							
Type							
Comment:						Date:	
Corrective Action:						Date:	

Inspected Facilities

Facility ID: <u>269644</u>	Type: <u>WELL</u>	API Number: <u>045-09389</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>287806</u>	Type: <u>WELL</u>	API Number: <u>045-13078</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>287807</u>	Type: <u>WELL</u>	API Number: <u>045-13077</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>287808</u>	Type: <u>WELL</u>	API Number: <u>045-13076</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>287809</u>	Type: <u>WELL</u>	API Number: <u>045-13075</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404655476	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7546044
701104766	Flowline integrity inspection 701104765 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7545984