

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2026

Submitted Date:

05/12/2026

Document Number:

715802279

**FIELD INSPECTION FORM**

Loc ID 319203 Inspector Name: Revas, Robbie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

- 24 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418033	WELL	PR	12/01/2017	OW	123-31819	SRC Pratt 34-29D	PR
418034	WELL	PR	12/01/2017	GW	123-31820	SRC Pratt 43-29D	PR
418035	WELL	PR	11/01/2022	GW	123-31821	SRC Pratt 29TD	PR
418036	WELL	PR	11/01/2022	GW	123-31822	SRC Pratt 29XD	PR
421226	WELL	PR	01/01/2026	OW	123-32857	SRC Pratt 29PD	PR
421239	WELL	PR	02/01/2025	OW	123-32862	SRC Pratt 33-29D	WK

**General Comment:**

[This is a field audit of the scout card, related documents and the location, Follow up to FIR Doc# 71420713 .](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:			Date: _____
Corrective Action:			

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	It appears to be stained soil at wellheads.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002..(2).D.		Date: 03/11/2026

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	IGNITOR/COMBUSTOR		
Comment:	6' vertical metal fence		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	6' vertical metal fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' vertical metal fence appears to be in disrepair x 6.		
Corrective Action:	Repair fencing to comply with Rule 603.h		Date: 04/04/2026

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	No change to permanent equipment from previous FIR, there are 6 mobile ECDs 1 mobile separator that have been moved onto location for Well liquids unloading.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
					40.017400,-105.022800
Comment: No change to tanks & berms from previous FIR, a water tank has been moved onto location for Well liquids unloading.					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
123-32862
123-31822
123-31819
123-31820
123-31821
123-32587

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 418033 Type: WELL API Number: 123-31819 Status: PR Insp. Status: PR

**Producing Well**

Comment: Pr; it appears the valves are in an open position.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 01/30/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Piped to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418034 Type: WELL API Number: 123-31820 Status: PR Insp. Status: PR

**Producing Well**

Comment: Pr; it appears the valves are in an open position.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: test date 4-3-2026 piped to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418035 Type: WELL API Number: 123-31821 Status: PR Insp. Status: PR

**Producing Well**

Comment: Pr; it appears the valves are in an open position.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 06/27/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Piped to surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 418036 Type: WELL API Number: 123-31822 Status: PR Insp. Status: PR

**Producing Well**

Comment: Pr; it appears the valves are in an open position.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 07/29/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Piped to surface

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 421226 Type: WELL API Number: 123-32857 Status: PR Insp. Status: PR

**Producing Well**

Comment: Pr; it appears the valves are in an open position.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/22/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: test date 4-30-2026 piped to surface

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 421239 Type: WELL API Number: 123-32862 Status: PR Insp. Status: WK

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Workover**

Comment: KPK WO rig 14 on location & Rigged up on the SRC Pratt 33-29d for well liquids unloading Form 42(liq)-00 404647172. No KP Kauffman workers on location.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p>ECMC Audit Report Summary                      WEATHER CONDITIONS: sunny, dry ground.                      On Tuesday, May 12, 2026 at approximately 11:50, I, Inspector Robbie Revas, conducted an on-site inspection                      Well Name: SRC PRATT 34-29D                      Operator: KP Kauffman                      Location ID: 319203                      County: WELD                      While there, I observed a producing facility.                      During this inspection the following possible compliance issues were observed:                      Housekeeping Rule 1002..(2).D.: stained soil at wellheads. Corrective Action Date: March 11, 2026.                      Housekeeping Rule 603.h.: Repair or re-install fencing. Corrective Action Date: April 4, 2026.                      The following compliance issue has been addressed:                      Housekeeping 606 dead vegetation has been cut &amp; removed from location.                      A follow up on this site audit needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of the audit report.</p>	revasr	05/12/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404656576	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7546971">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7546971</a>
715802280	Location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7546961">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7546961</a>