

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2026

Submitted Date:

05/14/2026

Document Number:

721100403

**FIELD INSPECTION FORM**

Loc ID 326457 Inspector Name: Blair, Jamie On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10679  
Name of Operator: LOGOS OPERATING LLC  
Address: 2010 AFTON PLACE  
City: FARMINGTON State: NM Zip: 87401

**Findings:**

- 18 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
General		Regulatory@logosresourcesllc.com	<a href="#">SJB inspect</a>
Labowskie, Steve		steve.labowskie@state.co.us	
Blair, Jamie		jamie.blair@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214459	WELL	PA	11/20/1975	DA	067-06062	FORD GAS UNIT A 2	PA
216531	WELL	PR	04/01/2015	GW	067-08137	IGNACIO 33-8 27A	PR

**General Comment:**

On Wednesday May 12 at 15:45 hours, southwest compliance inspection Jamie Blair performed a compliance inspection and audit. Corrective actions were identified pertaining to an unmarked riser and a meter that had not been calibrated in more than one year. A plugged and abandoned well was also identified on the site. See photos linked in the attachments.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	OK. 2 locked gates.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	On meter house. Note - Sign is still legible, but operator name label is beginning to peel. Emergency contact number remains legible, but label with number is also beginning to peel. If peeling continues will not comply with 605.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 hour - 866-598-6620 Emergency - 911.		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Cheat grass is abundant in reclamation area and west end of teardrop.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type			
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Deadman # & Marked	# 4		corrective date
Comment:	T post markers. One is bent over.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Cathodic protection		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		

Comment: <a href="#">on heated separator stack.</a>		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 3	
Comment: <a href="#">Solar telemetry at chemical treatment container, horizontal heated separator and meter run.</a>		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: <a href="#">accessible</a>		
Corrective Action:		Date:
Type: Other	# 1	
Comment: <a href="#">Wellhead.</a>		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: <a href="#">2/3/2025 Calibration date. Photo 5.</a>		
Corrective Action: <a href="#">Calibrate gas metering equipment annually to comply with rule 430.d.(1).</a>		Date: <a href="#">06/15/2026</a>
Type: Flow Line	# 3	
Comment: <a href="#">2" from well to separator. 2" nipples up to 3" at meter house. 3" nipples down to 2" downstream of meter run to off site midstream gathering with blank-flanged 3" unmarked riser behind barricade. Unmarked risers need to be marked by identifying what they are and tagged with OOSLAT. "LOTO" . Photo 9.</a>		
Corrective Action: <a href="#">Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser to comply with 1105.b</a>		Date: <a href="#">05/28/2026</a>

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		37.122737,-107.699569
Comment: <a href="#">Open topped with expanded metal wildlife protection screen.</a>					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	125 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:		Date:		

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 214459 Type: WELL API Number: 067-06062 Status: PA Insp. Status: PA

Facility ID: 216531 Type: WELL API Number: 067-08137 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 04/28/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: Accessible

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Unmarked riser and gas meter calibration outside of 1 year time frame. Photos included as link in the attachment.</a>	blairj1	05/14/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404659033	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7548616">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7548616</a>
721100406	photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7548613">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7548613</a>