

Inspection Photos
Location Name: Mill Iron 1-11
API: 05-125-06316



Location and Erosion

Lease sign

Inspection Photos
Location Name: Mill Iron 1-11
API: 05-125-06316



Meter run and Wellhead



Meter run and PU

Inspection Photos
Location Name: Mill Iron 1-11
API: 05-125-06316



Buried tank and Unmarked risers

Tank sign

Inspection Photos
Location Name: Mill Iron 1-11
API: 05-125-06316



Meter shed



Calibration stickers