

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2026

Submitted Date:

05/21/2026

Document Number:

708700154

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Kosola, Jason On-Site Inspection
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430890	UIC WATER TRANSFER STATION	AC	11/26/2012		-	Ballatine Transfer Station 430890	EI

General Comment:

[This is an environmental inspection to document site status.](#)

[Secondary containment around tanks is inadequate to contain a spill - there is a large hole in SW corner. See attached photos.](#)

[Tanks are not labeled.](#)

Location

Overall Good:

Signs/Marker:

	Type TANK LABELS/PLACARDS		
	Comment: Sign or label not posted on tanks.		
	Corrective Action: Install sign to comply with Rule 605.h.	Date: <u>07/21/2026</u>	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: _____	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment: <input style="width: 95%;" type="text"/>					
Corrective Action:					Date: <input style="width: 15%;" type="text"/>

Paint

Condition	<input style="width: 95%;" type="text"/>
Other (Content)	<input style="width: 95%;" type="text"/>
Other (Capacity)	<input style="width: 95%;" type="text"/>
Other (Type)	<input style="width: 95%;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal		Walls Insufficient	Base Insufficient	Inadequate
Comment: Inadequate berms around tanks.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1).				Date: <u>06/10/2026</u>

Venting:

Yes/No	<input style="width: 95%;" type="text"/>		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: <input style="width: 15%;" type="text"/>	

Flaring:

Type	<input style="width: 95%;" type="text"/>		
Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date: <input style="width: 15%;" type="text"/>	

Inspected Facilities

Facility ID: 430890 Type: UIC WATER API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708700155	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556333