

ECMC Inspection Photos - KP Kauffman
Location ID 450409 – Lanson Farms Battery
Date 05/20/2026



KPK Lanson Farms Battery and signage.



View from location looking north toward fenced excavation at the Western Midstream gas meter run. The KPK outbuilding houses a flowline manifold.

ECMC Inspection Photos - KP Kauffman
Location ID 450409 – Lanson Farms Battery
Date 05/20/2026



View from location looking south at fenced excavation on the west side of the Western Midstream gas meter run. The KPK outbuilding houses a flowline manifold.



Closer view of (2) 3" fiberglass flowlines operated by KPK exposed in excavation; standing ground water in excavation.

ECMC Inspection Photos - KP Kauffman
Location ID 450409 – Lanson Farms Battery
Date 05/20/2026



Close up view of (2) KPK 3" fiberglass flowlines unearthed in the excavation. Standing groundwater in excavation makes it difficult to see the flowlines in any detail.



Photo of KPK Lanson Farms flowline manifold in outbuilding.