

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2026

Submitted Date:

05/14/2026

Document Number:

701104776

FIELD INSPECTION FORM

Loc ID: 324469 Inspector Name: LONGWORTH, MIKE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 77330
 Name of Operator: SG INTERESTS I LTD
 Address: 100 WAUGH DR SUITE 400
 City: HOUSTON State: TX Zip: 77007

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|---------------|-------|----------------------------|---------------------|
| , SGInterests | | inspection@sginterests.com | Inspection mail box |
| Burn, Diana | | diana.burn@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 271432 | WELL | PR | 02/01/2011 | GW | 051-06057 | FEDERAL 11-90-24 1 | EG |

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
 Open ended pipe swedge at separator unit with out plug/cap.
 Comply with Rule 603.i.- Loadlines - All loadlines will be bullplugged or capped.
 CA Date: 05/21/2026

Location

Lease Road:

| | | | |
|-------------------|--------|--|-------|
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|--|-------|
| Type | BATTERY | | |
| Comment: | Battery sign is faded. | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Label hazard number are faded on separator unit. | | |
| Corrective Action: | | | Date: |

Emergency Contact Number:

| | | | |
|--------------------|-----|--|-------------|
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|-------|--|-------|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|--|------|--------|--|--|--|
| In Containment: | No | | | | |
| Comment: | | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | | |

Equipment:

| | | | |
|--------------------|---|--|-------------------------|
| | | | corrective date |
| Type: | Horizontal Heated Separator # 1 | | |
| Comment: | Open ended pipe swedge at separator unit with out plug/cap. | | |
| Corrective Action: | Comply with Rule 603.i.- Loadlines - All loadlines will be bullplugged or capped. | | Date: <u>05/21/2026</u> |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|------------|---|----------|------------------|---------|--------|
| CONDENSATE | 4 | 400 BBLS | HEATED STEEL AST | | , |

| | | |
|--------------------|--|-------|
| Comment: | Rust and corrosion on man hatch bottom set of bolts and around bottom of tank. Rusted pipes and fittings. | |
| Corrective Action: | | Date: |

Paint

| | | |
|------------------|------------|--|
| Condition | Inadequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 271432 Type: WELL API Number: 051-06057 Status: PR Insp. Status: EG

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 404660330 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7549605 |
| 701104777 | Flowline integrity inspection 701104776 photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7549602 |