

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/08/2026

Submitted Date:

05/15/2026

Document Number:

701104778

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
324490 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 77330
Name of Operator: SG INTERESTS I LTD
Address: 100 WAUGH DR SUITE 400
City: HOUSTON State: TX Zip: 77007

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, SGInterests		inspection@sginterests.com	Inspection mail box
Whittington, Ellice		ellice.whittington@state.co.us	
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295631	WELL	IJ	03/30/2023	DSPW	051-06084	FEDERAL 24-2 WDW	EG

General Comment:

Flowline Integrity Inspection and Tank Integrity Inspection
Labels on the 2-500 gallon tanks and buried 90 bbl tank are missing necessary information.
Corrective Action: Install sign to comply with Rule 605.h.
CA Date: 06/19/2026
Heat element assembly plate has paint deterioration and rust corrosion occurring.
Seep beginning on bottom of tank.
Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.
CA Date: 05/20/2026

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Labels on the 2-500 gallon tanks and buried 90 bbl tank are missing necessary information.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/19/2026

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	8	400 BBLs	HEATED STEEL AST		,
Comment:	Heat element assembly plate has paint deterioration and rust corrosion occurring. Seep beginning on bottom of tank.				
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.				Date: 05/20/2026

Paint

Condition	Inadequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficent			
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 295631 Type: WELL API Number: 051-06084 Status: IJ Insp. Status: EG

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404660332	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7549606
701104779	Flowline integrity inspection 701104778 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7549604