

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/11/2026

Submitted Date:

05/15/2026

Document Number:

701104784

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
315354 \_\_\_\_\_ LONGWORTH, MIKE \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 3975  
Name of Operator: ARGALI EXPLORATION COMPANY  
Address: PO BOX 416  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
, Inspections		argaliexplorationcompany@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230683	WELL	SI	07/01/2025	GW	103-08351	FEDERAL B-10-3-101-S	EG

**General Comment:**

Flowline Integrity Inspection and Tank Integrity Inspection  
No "NO SMOKING" sign seen at location.  
Corrective Action: Comply with Rule 610.f.  
CA Date: 06/19/2026  
Unused riser at meter shed with open ended pipe. No OOSLAT in place.  
Unused 1" riser inside of wood vault with no plug. No OOSLAT in place.  
Corrective Action: Comply with Rule 1101.a.(3)  
CA Date: 06/19/2026

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	No "NO SMOKING" sign seen at location.		
Corrective Action:	Comply with Rule 610.f.	Date:	06/19/2026

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

Type: Flow Line	# 1		corrective date
Comment:	Unused riser at meter shed with open ended pipe. No OOSLAT in place. Unused 1" riser inside of wood vault with no plug. No OOSLAT in place.		
Corrective Action:	Comply with Rule 1101.a.(3)	Date:	06/19/2026

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230683 Type: WELL API Number: 103-08351 Status: SI Insp. Status: EG

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404660699	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7549856">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7549856</a>
701104785	Flowline integrity inspection 701104784 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7549852">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7549852</a>