

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/13/2026

Submitted Date:

05/15/2026

Document Number:

701104794

FIELD INSPECTION FORM

Loc ID 334728 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Energy, QB		ecmc.inspections@qb-energy.com	QB Inspection mail box

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276410	WELL	SI	12/01/2025	GW	045-10450	PUCKETT 22B-7	EG
290731	WELL	SI	12/01/2025	GW	045-14195	PUCKETT 22C-7D	EG
290732	WELL	SI	12/01/2025	GW	045-14194	PUCKETT 22D-7D	EG
290733	WELL	SI	12/01/2025	GW	045-14193	PUCKETT 22A-7D	EG

General Comment:

Flowline Integrity Spill Response Inspection and Tank Integrity Inspection
Spill name Commingled Dumpline Mesa 23 id# 493974
Spill Description: During Annual Pressure Test the Commingled Dumpline failed. No visible impacts at surface. Failure point Lat/Long was reported at the mid-point of the Dumpline, as failure may be close to the Separator or tank. Separator is shut-in and line is isolated. Dumplines at separators have been excavated.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	HEATED STEEL AST		,
Comment:	Paint deterioration and rust around bottom of tank.				
Corrective Action:				Date:	

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	<input type="text"/>			

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 276410 Type: WELL API Number: 045-10450 Status: SI Insp. Status: EG

Flowline

#1	Type: Dump Line	2 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

ECMC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: **Spill name Commingled Dumpline Mesa 23 id# 493974**
Spill Description: During Annual Pressure Test the Commingled Dumpline failed. No visible impacts at surface. Failure point Lat/Long was reported at the mid-point of the Dumpline, as failure may be close to the Separator or tank. Separator is shut-in and line is isolated.
Dumplines at separators have been excavated. There appears to several holes of dumplines.

Corrective Action: **In the Supplemental Form 19, identify the root cause of the failure and explain how recurrence on this pipeline and the other pipelines associated with this facility will be prevented, per Rule 912.d.(3).**

Date:

Facility ID: 290731 Type: WELL API Number: 045-14195 Status: SI Insp. Status: EG

Facility ID: 290732 Type: WELL API Number: 045-14194 Status: SI Insp. Status: EG

Facility ID: 290733 Type: WELL API Number: 045-14193 Status: SI Insp. Status: EG

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404660943	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550057
701104795	Flowline integrity inspection 701104794 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7550054