

Inspection Photos

Location Name: Simcoe – Linder A 1
Location ID: API 05-067-07419



1. Well Sign.

2. Wellhead, pump jack and solar telemetry behind steel cattle panel fence. There is also a black steel mesh cage around the drive portion of the pump jack.

Inspection Photos

Location Name: Simcoe – Linder A 1

Location ID: API 05-067-07419



3. Lube oil container over spill prevention next to valve riser.



4. Solar telemetry.

Inspection Photos

Location Name: Simcoe – Linder A 1

Location ID: API 05-067-07419



5. Well gas prime mover, pump jack, and wellhead.

6. Wellhead.

Inspection Photos

Location Name: Simcoe – Linder A 1

Location ID: API 05-067-07419



9. Vertical heated separator NFPA labels.



10. Solar telemetry for production equipment.