

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2026

Submitted Date:

05/22/2026

Document Number:

721100401

FIELD INSPECTION FORM

Loc ID: 333629 Inspector Name: Blair, Jamie On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Simcoe/Mach NR		ehsinspections@machnr.com	
Blair, Jamie		jamie.blair@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215814	WELL	PR	03/23/1990	CBM	067-07419	LINDNER A 1	PR

General Comment:

At 18:15 hours on Tuesday, May 12, 2026 southwest compliance specialist Jamie Blair performed a compliance inspection and audit of the Simcoe Linder A1 well. The well was operating during the inspection. No corrective actions were identified. Photos are included as a link in the attachments section of this report.

Location			
Lease Road:			
Type	Access		
comment:	Follows canal 1 mile south from county road. Road goes through middle of location.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	On production equipment fence. Photo 1.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	24 Hour Call Center (970) 247-6916 Emergency = 911		
Corrective Action:			Date:
Good Housekeeping:			
Type	OTHER		
Comment:	Vegetation sparse in area from cattle grazing.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Cattle panel fence around production equipment.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Cattle panel fence around wellhead and pump jack, with secondary inner 4" wire mesh cage surrounding pinch points on pump jack to prevent cattle injury.		
Corrective Action:			Date:
Type	OTHER		
Comment:	cattle panel around solar telemetry for production equipment.		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Bradenhead	# 1		
Comment:	accessible		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	well gas power.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	walking beam		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	3" production equipment flow lines by heated separator.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator heater stack		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Only 3 anchors. No anchor NE of wellhead. Would be in road if present.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	In structure shared with VHS. 7/15/25 cal date.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Solar telemetry. One for pump jack and wellhead, one for production equipment.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215814 Type: WELL API Number: 067-07419 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 07/15/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Accessible

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
721100402	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7557690