

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1275 From entrance to location




Photo # 1276 Battery sign

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1277 Location



Photo # 1278 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1279 Location




Photo # 1280 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1281 Location



Photo # 1282 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766




Photo # 1283 Location



Photo # 1284 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1285 Location



Photo # 1286 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1287 Location



Photo # 1288 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766




Photo # 1289 Location




Photo # 1290 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1291 Location



Photo # 1292 Location

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1293 Label on rig tank lacks capacity



Photo # 1294 Frac tank lacks required labeling

Inspection/Audit Photos

Location Name: QB ENERGY OPERATING LLC CHEVRON 44-5D (PARACHUTE CREEK 8)

Location ID: 335766



Photo # 1295 Frac tank lacks required labeling