

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2026

Submitted Date:

05/18/2026

Document Number:

713401422

**FIELD INSPECTION FORM**

Loc ID 315098 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10779  
Name of Operator: SCOUT ENERGY MANAGEMENT LLC  
Address: 13800 MONTFORT DRIVE SUITE 100  
City: DALLAS State: TX Zip: 75240

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Wiley, Mikel		Mikel.Wiley@scoutep.com	
Rosado, Sydney		Sydney.Rosado@scoutep.com	
Sanford, Anita		anita.sanford@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230251	WELL	PR	05/01/2018	OW	103-07910	RIGBY A 3X	PR

**General Comment:**

[This is a Field Inspection/audit of the scout card, related documents and the location.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wellhead sign lacks public road used to access the well. No tank battery on location		
Corrective Action:	Comply with CECMC rule 605		Date: 06/18/2026

<b>Emergency Contact Number:</b>			
Comment:	970-675-3700/911		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>				corrective date
Type:	Ancillary equipment	# 1		
Comment:	Control panel			
Corrective Action:				Date:
Type:	Deadman # & Marked	# 6		
Comment:				
Corrective Action:				Date:
Type:	Ancillary equipment	# 1		
Comment:	Chemical tank			
Corrective Action:				Date:
Type:	Submersible Pump	# 1		
Comment:				
Corrective Action:				Date:
Type:	Bradenhead	# 1		

Comment:	Bradenhead valve is accessible/equipped with gauge		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 230251 Type: WELL API Number: 103-07910 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well equipped with ESP](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
Compaction						Light compaction
				Material Handling And Spill Prevention		Chemical tank containment 1/2 full of fluid
		Compaction				Light compaction

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 05/14/2026 at approximately 13:39 hours, Compliance Inspector Dusty Popejoy conducted a follow up inspection/audit at SCOUT ENERGY MANAGEMENT LLC RIGBY A #3X at Location ID #315098 in Rio Blanco County, Colorado.</p> <p>Please refer to inspection/audit 713401029 conducted on 08/25/2025, previous corrective action has been completed.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed normal production operations.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Signs/Marker - Wellhead sign lacks public road used to access the well with a CA date of 06/18/2026</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	05/18/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404662927	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551788">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551788</a>
713401423	713401422 Inspection-Audit Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551787">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551787</a>