

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2026

Submitted Date:

05/18/2026

Document Number:

714300391

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: Brown, Kari On-Site Inspection   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name    | Phone | Email                   | Comment                           |
|-----------------|-------|-------------------------|-----------------------------------|
| Mickelson, Erik |       | Erik_Mickelson@oxy.com  | <a href="#">Oxy Environmental</a> |
| ,               |       | ECMCInspections@Oxy.com | <a href="#">All Inspections</a>   |

**Inspected Facilities:**

| Facility ID | Type             | Status | Status Date | Well Class | API Num | Facility Name                    | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|----------------------------------|-------------|
| 493454      | SPILL OR RELEASE | AC     |             |            | -       | Babcock 32, 33, 14, 23-33HZ      | EI          |
| 493915      | SPILL OR RELEASE | AC     |             |            | -       | BABCOCK 32 33 14 23-33HZ FAC BT2 | EI          |

**General Comment:**

This is an environmental inspection to determine progress on Spill ID 493915 & Spill ID 493454/Remediation Project No 44827. Any corrective actions from previous inspections, NOAVs, or COAs that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

**Inspected Facilities**

Facility ID: 493454 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Facility ID: 493915 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: Spill ID 493454: Deep excavation open at the former separator location. Water was observed in the bottom of the open excavation; no sheen was observed on the water. No obvious hydrocarbon impacts were observed in-situ. Operator will comply with the implementation schedule and Conditions of Approval for all remaining remediation of soil impacts, reclamation and reporting established in the ECMC Remediation Project No. 44827.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

\_\_\_\_\_

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Waste Management:**

| Type | Management                               | Condition | GPS (Lat) | (Long) |             |
|------|--|-----------|-----------|--------|-------------|
|      |  |           |           |        |             |
|      | Comment: No E&P waste stored on location |           |           |        |             |
|      | Corrective Action                        |           |           |        | Date: _____ |

**Spill/Remediation:**

Comment: Spill ID 493915:  
A shallow excavation is present adjacent to separators. No obvious hydrocarbon impacts were observed in-situ.

Corrective Action: Operator shall provide an updated Form 27 for Remediation #44827 with a workplan and timeline for remediation of Spill ID 493915. Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404662885    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551734">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551734</a> |
| 714300392    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551729">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7551729</a> |