

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2026

Submitted Date:

05/19/2026

Document Number:

719201163

**FIELD INSPECTION FORM**

Loc ID 316060 Inspector Name: Gaasche, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 16700  
Name of Operator: CHEVRON USA INC  
Address: CHEVRON USA INC  
City: GRAND JUNCTION State: CO Zip: 81506

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, CHEVRON		andrewolson@chevron.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232022	WELL	PA	10/06/2022	OW	103-09693	WILSON CREEK UNIT 69	RI
316060	LOCATION	CL			-	WILSON CREEK UNIT-62N94W 4NWSE	RI

**General Comment:**

On 05/14/2026, NW Reclamation Specialist Emily Gaasche conducted a final reclamation inspection at Chevron USA Inc's WILSON CREEK UNIT-62N94W/4NWSE (Wilson Creek Unit #69) location in Rio Blanco County, Colorado. The location is Federal Surface.

The location is within CPW High Priority Habitat: Elk Production Area, Mule Deer Migration Corridor.

The following compliance issues were observed during this inspection:  
-Noxious weeds/undesirable plant species

Refer to the Location, Reclamation and Stormwater sections of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	Multiple types of noxious weeds and undesirable plant species are present throughout the site, such as cheatgrass, clover, purple mustard, clasping pepperweed, houndstongue, common mullein, and weedy annual mustards. Weed establishment may be hindering progression towards 1004 requirements. Weed control is required.		
Corrective Action:	Comply with Rule 606.c. and 1004.f.	Date:	06/19/2026

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 232022 Type: WELL API Number: 103-09693 Status: PA Insp. Status: RI

Facility ID: 316060 Type: LOCATION API Number: - Status: CL Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured Pass

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present **Fail** Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% 20  
 TRANSECT RESULTS OF REFERENCE AREA% 54  
 TOTAL % OF DESIRABLE VEGETATION COVER 37  
 VEGETATIVE COVER FAIL

Comment:

Pursuant to Form 6(s) #403598498, well 103-09693 was plugged and abandoned on 10/6/2022. All surface equipment has been removed, the location recontoured and reclaimed. The location is primarily composed of cheatgrass and clover. Secondary species include Rocky Mtn penstemon, thickspike wheatgrass and prairie Junegrass; tertiary species are weedy annual mustards, clasping pepperweed, purple mustard, smooth brome and common mullein.

A vegetation transect was performed at this location. 37% of vegetative cover is desirable/perennial. Vegetation is non-uniform in some areas. Weed establishment may be hindering progress towards 1004 reclamation requirements. Weed control is required; see Good Housekeeping section for weed control CA and date.

Corrective Action:  Date \_\_\_\_\_

Overall Final Reclamation  Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<p><b>Additional Reclamation Comments:</b>                      The access road leading to the location has not yet been reclaimed pursuant to 1004 rules. The road is currently in use by the Operator and Surface Owner. A Variance request pursuant to Rule 502.b. will need to be submitted to the Commission to leave the road unreclaimed.</p> <p>A follow-up inspection will be conducted to assess weed control efforts and evaluate compliance with 1004 reclamation requirements.</p>	gaaschee	05/19/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404664945	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7553488">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7553488</a>
719201165	Vegetation Transect Data	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7553483">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7553483</a>
719201166	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7553484">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7553484</a>